

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
111-90-0		"CARBITOL" SOLVENT	D		
111-15-9		"CELLOSOLVE" ACETATE	D		
110-80-5		"CELLOSOLVE" SOLVENT	D		
	2-	(2,4,6-TRINITROPHENYL)ETHYL ACETATE (1% IN ACETONE & BENZENE)	S		
12427-38-2		AAMANGAN	W		
88-85-7		AATOX	S		
40487-42-1		AC 92553	S		
105-57-7		ACETAL	D		
75-07-0		ACETALDEHYDE	D		
105-57-7		ACETALDEHYDE, DIETHYL ACETAL	D		
108-05-4		ACETIC ACID ETHENYL ESTER	D		
108-05-4		ACETIC ACID VINYL ESTER	D		
75-07-0		ACETIC ALDEHYDE	D		
101-25-7		ACETO DNPT	T		
126-84-1		ACETONE DIETHYL ACETAL	D		
108-05-4		ACETOXYETHYLENE	D		
108-05-4	1-	ACETOXYETHYLENE	D		
37187-22-7		ACETYL ACETONE PEROXIDE, <=32% AS A PASTE	T		
37187-22-7		ACETYL ACETONE PEROXIDE, <=42%	T		
37187-22-7		ACETYL ACETONE PEROXIDE, >42%	T	S	
644-31-5		ACETYL BENZOYL PEROXIDE (SOLID OR MORE THAN 45% IN SOLUTION)	T	S	
644-31-5		ACETYL BENZOYL PEROXIDE, <=45%	T		
506-96-7		ACETYL BROMIDE	W		
75-36-5		ACETYL CHLORIDE	W		
		ACETYL CYCLOHEXANE SULFONYL PEROXIDE (>82% WITH <12% WATER)	T	S	
3179-56-4		ACETYL CYCLOHEXANE SULFONYL PEROXIDE, <=32%	T		
3179-56-4		ACETYL CYCLOHEXANE SULFONYL PEROXIDE, <=82%	T		
674-82-8		ACETYL KETENE (POISON INHALATION HAZARD)	D		
110-22-5		ACETYL PEROXIDE, <=27%	T		
110-22-5		ACETYL PEROXIDE, SOLID, OR MORE THAN 27% IN SOLUTION	T	S	
927-86-6		ACETYLCHOLINE PERCHLORATE	O	S	
74-86-2		ACETYLENE	D		
74-86-2		ACETYLENE (LIQUID)	D		
		ACETYLENE SILVER NITRATE	D		
107-02-08		ACRALDEHYDE (POISON INHALATION HAZARD)	D		
79-10-7		ACROLEIC ACID	D		
107-02-08		ACROLEIN, INHIBITED (POISON INHALATION HAZARD)	D		
107-02-08		ACRYLALDEHYDE (POISON INHALATION HAZARD)	D		
79-10-7		ACRYLIC ACID	D		
141-32-2		ACRYLIC ACID BUTYL ESTER	D		
140-88-5		ACRYLIC ACID ETHYL ESTER	D		
96-33-3		ACRYLIC ACID METHYL ESTER	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
107-02-08		ACRYLIC ALDEHYDE (POISON INHALATION HAZARD)	D		
107-13-1		ACRYLON	D		
107-13-1		ACRYLONITRILE	D		
814-68-6		ACRYLOYL CHLORIDE	D		
814-68-6		ACRYLYL CHLORIDE	D		
37221-33-3		ADN	S		
106-92-3		AGE	D		
12427-38-2		AGROX (FLOWABLE; N-M)	W		
88-85-7		AI3-01122	S		
77-73-6		AI3-03386	D		
101-68-8		AI3-15256	W		
924-42-5		AI3-25447	D		
26628-22-8		AI3-50436	S	T	
75-78-5		AI3-51462	A	W	
75-79-6		AI3-51465	W	A	
126-98-7		AI3-52399	D		
7722-84-1		ALBONE (OVER 60% PEROXIDE)	O	S	
10049-04-4		ALCIDE	S		
51-28-5		ALDIFEN (DRY)	S		
107-02-08		ALLYL ALDEHYDE (POISON INHALATION HAZARD)	D		
557-40-4		ALLYL ETHER	D		
106-92-3		ALLYL GLYCIDYL ETHER	D		
1730-25-2		ALLYL MAGNESIUM BROMIDE (IN SOLVENT)	W		
2622-05-1		ALLYL MAGNESIUM CHLORIDE (IN SOLVENT)	W		
1746-13-0		ALLYL PHENYL ETHER	D		
107-37-9		ALLYL TRICHLOROSILANE	D		
3917-15-5		ALLYL VINYL ETHER	D		
74-99-7		ALLYLENE	D		
106-92-3	1-	ALLYLOXY-2,3-EPOXYPROPANE	D		
105-74-8		ALPEROX-F	T		
16962-07-5		ALUMINUM BOROHYDRIDE	A	W	
2269-22-9		ALUMINUM BUTOXIDE	W		
1299-86-1		ALUMINUM CARBIDE	W		
15477-33-5		ALUMINUM CHLORATE	O		
7446-70-0		ALUMINUM CHLORIDE (ANHYDROUS)	W		
96-10-6		ALUMINUM DIETHYL MONOCHLORIDE	A		
		ALUMINUM DIMETHYL CHLORIDE	W		
		ALUMINUM DROSS, WET OR HOT	D		
		ALUMINUM FERROSILICON POWDER	W		
7784-21-6		ALUMINUM HYDRIDE	W		
7784-23-8		ALUMINUM IODIDE	W		
20859-73-8		ALUMINUM MONOPHOSPHIDE	W		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
13473-90-0		ALUMINUM NITRATE	O		
24304-00-5		ALUMINUM NITRIDE	W		
20859-73-8		ALUMINUM PHOSPHIDE	W		
7429-90-5		ALUMINUM POWDER, UNCOATED	W		
		ALUMINUM SILICON POWDER, UNCOATED	W		
16962-07-5		ALUMINUM TETRAHYDROBORATE	A	W	
2269-22-9		ALUMINUM TRIBUTOXIDE	W		
7446-70-0		ALUMINUM TRICHLORIDE	W		
97-93-8		ALUMINUM TRIETHYL	A	W	
75-24-1		ALUMINUM TRIMETHYL	A	W	
13473-90-0		ALUMINUM TRINITRATE	O		
2269-22-9		ALUMINUM TRI-SEC-BUTOXIDE	W		
12042-38-5		ALUMINUM-MAGNESIUM ALLOY	W		
2269-22-9		ALUMINUM-SEC-BUTOXIDE	W		
420-04-2		AMIDOCYANOGEN	T		
	2-	AMINO-3,5-DINITROTOLUENE (1% SOLUTION IN ACETONE & BENZENE)	S		
96-91-3	2-	AMINO-4,6-DINITROPHENOL (WET)	S		
12164-94-2		AMMONIUM AZIDE	D		
		AMMONIUM BROMATE	D		
131-74-8		AMMONIUM CARBAZOATE (WET >10% WATER)	S		
16774-21-3		AMMONIUM CERIUM (IV) NITRATE	O		
10192-29-7		AMMONIUM CHLORATE	D		
37221-33-3		AMMONIUM DINITRAMIDE	S		
		AMMONIUM FULMINATE	D		
16774-21-3		AMMONIUM HEXANITRATOCERATE	O		
6484-52-2		AMMONIUM NITRATE (WITH MORE THAN 0.2% COMBUSTIBLE SUBSTANCES)	S		
6484-52-2		AMMONIUM NITRATE DRY	O		
6484-52-2		AMMONIUM NITRATE FERTILIZERS	O	S	
6484-52-2		AMMONIUM NITRATE-FUEL OIL MIXTURE (CONTAINING ONLY PRILLED AMMONIUM NITRATE & FUEL OIL)	S		
13446-48-5		AMMONIUM NITRITE	D		
7790-98-9		AMMONIUM PERCHLORATE (DRY)	O	S	
7790-98-9		AMMONIUM PERCHLORATE (WET)	O	S	
13446-10-1		AMMONIUM PERMANGANATE	D		
131-74-8		AMMONIUM PICRATE (DRY)	S		
131-74-8		AMMONIUM PICRATE (WET >10% WATER)	S		
131-74-8		AMMONIUM PICRONITRATE (WET >10% WATER)	S		
693-65-2		AMYL ETHER	D		
3425-61-4	TERT-	AMYL HYDROPEROXIDE, <=88%	T		
1002-16-0		AMYL NITRATE	O		
110-46-3		AMYL NITRITE	A		
68299-16-1	T-	AMYL PEROXY NEODECANOATE, <=77%	T		
686-31-7	TERT	AMYL PEROXY-2-ETHYL HEXANOATE, <=100%	T		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
	TERT-	AMYL PEROXY-2-ETHYLHEXYL CARBONATE, <=100%	T		
	TERT	AMYL PEROXYACETATE, <=62%	T		
4511-39-1	T-	AMYL PEROXYBENZOATE, <=96%	T		
29240-17-3	T-	AMYL PEROXYPIVALATE, <=77%	T		
68860-54-8	TERT-	AMYLPEROXY-3,5,5-TRIMETHYLHEXANOATE, <=100%	T		
55-63-0		ANGIBID	S		
78-11-5		ANGICAP (DRY)	D		
55-63-0		ANGININE	S		
55-63-0		ANGIOLINGUAL	S		
78-11-5		ANGITET (DRY)	D		
55-63-0		ANGORIN	S		
10049-04-4		ANTHIUM DIOXIDE	S		
		ANTIMONY SULFIDE AND A CHLORATE, MIXTURES OF	D		
534-52-1		ANTINONIN	S		
7632-00-0		ANTI-RUST	O		
78-11-5		ANTORA (DRY)	D		
7697-37-2		AQUAFORTIS (40% OR LESS)	O		
7697-37-2		AQUAFORTIS (OVER 40%)	O		
		AQUAFORTIS, FUMING (POISON INHALATION HAZARD)	O		
107-02-08		AQUALIN (POISON INHALATION HAZARD)	D		
106-99-0		AR	D		
106-99-0		AR 25339-57-5	D		
534-52-1		ARBOROL	S		
78-11-5		ARCOTRATE (DRY)	D		
88-85-7		ARETTT	S		
7784-36-3		ARSENIC (V) FLUORIDE (POISON INHALATION HAZARD)	W		
7784-36-3		ARSENIC PENTAFLUORIDE (POISON INHALATION HAZARD)	W		
		ARSENIC SULFIDE AND A CHLORATE, MIXTURES OF	D		
7440-66-6		ASARCO L 15	W		
512-85-6		ASCARIDOLE (ORGANIC PEROXIDE)	T		
97-93-8		ATC	A	W	
7775-09-9		ATLACIDE	O		
151-56-4		AZACYCLOPROPANE, INHIBITED (POISON INHALATION HAZARD)	D		
		AZAUROLIC ACID (SALT OF) (DRY)	D		
		AZIDO GUANIDINE PICRATE (DRY)	D		
		AZIDO HYDROXY TETRAZOLE(MERCURY AND SILVER SALTS)	D		
	3-	AZIDO-1,2-PROPYLENE GLYCOL DINITRATE	D		
	5-	AZIDO-1-HYDROXY TETRAZOLE	D		
		AZIDODITHIOCARBONIC ACID	D		
		AZIDOETHYL NITRATE	D		
334-88-3		AZIMETHYLENE	D		
151-56-4		AZIRAN, INHIBITED (POISON INHALATION HAZARD)	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
1072-52-2		AZIRIDINE ETHANOL	D		
151-56-4		AZIRIDINE, INHIBITED (POISON INHALATION HAZARD)	D		
26628-22-8		AZIUM	S	T	
13472-08-7	2,2-	AZOBIS(2-METHYLBUTYRONITRILE)	T		
78-67-1	2,2-	AZOBIS(2-METHYLPROPANENITRILE)	T		
78-67-1	2,2-	AZOBIS(2-METHYLPROPIONITRILE)	T		
2638-94-0	4,4'-	AZOBIS(4-CYANOVALERIC ACID)	T		
20858-12-2	2,2-	AZOBIS(DIMETHYLENEISOBUTYRAMIDINE)	T		
20858-12-2	2,2'-	AZOBIS(N,N'-DIMETHYLENEISOBUTYRAMIDINE)	T		
20858-12-2	2,2'-	AZOBIS(N,N'-DIMETHYLENEISOBUTYRAMIDINE)	T		
20858-12-2	2,2'-	AZOBIS[2-(2-IMIDAZOLIN-2YL)PROPANE]	T		
78-67-1	2,2-	AZOBIS-2,4-DIMETHYL PENTANENITRILE	T		
15545-97-8	2,2-	AZOBIS-2,4-DIMETHYL-4-METHOXY PENTANENITRILE	T		
15545-97-8	2,2-	AZOBIS-2,4-DIMETHYL-4-METHOXY VALERONITRILE	T		
4419-11-8	2,2-	AZOBIS-2,4-DIMETHYLVALERONITRILE	T		
2638-94-0	4,4'-	AZOBIS-4-CYANOPENTANOIC ACID	T		
123-77-3		AZOBISFORMAMIDE (SELF-REACTIVE FORMULATION)	T		
78-67-1	2,2-	AZOBISISOBUTYRONITRILE	T		
502-98-7		AZOCHLORAMIDE (SALTS OF)(DRY)	D		
15545-97-8	2-2"	AZODI-(2,4-DIMETHYL-4-METHOXYVALERONITRILE)	T		
4419-11-8	2,2-	AZODI(2,4-DIMETHYLVALERONITRILE)	T		
13472-08-7	2,2'-	AZODI(2-METHYLBUTYRONITRILE)	T		
	2,2-	AZODI(ETHYL-2-METHYLPROPIONATE)	T		
	1,1'-	AZODI-(HEXAHYDROBENZONITRILE)	T		
78-67-1		AZODI(ISOBUTYRONITRILE)	T		
123-77-3		AZODICARBONAMIDE (SELF-REACTIVE FORMULATION)	T		
		AZOTETRAZOLE (DRY)	D		
7697-37-2		AZOTIC ACID (40% OR LESS)	O		
7697-37-2		AZOTIC ACID (OVER 40%)	O		
		AZOTIC ACID, FUMING (POISON INHALATION HAZARD)	O		
		BAMO/AMMO	S		
78-11-5		BARITRATE (DRY)	D		
7440-39-3		BARIUM (ELEMENT)	W		
18810-58-7		BARIUM AZIDE (DRY)	S		
18810-58-7		BARIUM AZIDE (WET >50% WATER)	S		
13967-90-3		BARIUM BROMATE	O		
13477-00-4		BARIUM CHLORATE	O		
1304-28-5		BARIUM MONOXIDE	W		
10022-31-8		BARIUM NITRATE	O		
1304-28-5		BARIUM OXIDE	W		
13465-95-7		BARIUM PERCHLORATE	O		
1304-28-5		BARIUM PROTOXIDE	W		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
		BARIUM STYPHNATE	S		
12427-38-2		BASF-MANEBSPRITZPULVER	W		
62202-86-2		BEM	A	W	
94-36-0		BENOX A-70	T		
582-61-6		BENAZIDE, BENZOIC ACID AZIDE	D		
		BENZENE TRIOZONIDE	D		
121-14-2		BENZENE,1-METHYL-2,4-DINITRO-	S		
136-35-6		BENZENEAZOANILIDE	S		
100-34-5		BENZENEDIAZONIUM CHLORIDE (DRY)	D		
617-96-7		BENZENEDIAZONIUM NITRATE (DRY)	D		
274-07-7	1,3,2	BENZODIOXABOROLE	W		
		BENZOXIDIAZOLES (DRY)	D		
582-61-6		BENZOYL AZIDE	D		
94-36-0		BENZOYL PEROXIDE, <=52% AS A PASTE	T		
94-36-0		BENZOYL PEROXIDE, <=56.5% AS A PASTE WITH 15% WATER	T		
94-36-0		BENZOYL PEROXIDE, <=62% WITH 10% WATER	T		
94-36-0		BENZOYL PEROXIDE, <=77% WITH 23% WATER	T		
94-36-0		BENZOYL PEROXIDE, >35-52%	T		
94-36-0		BENZOYL PEROXIDE, >36-42%	T		
94-36-0		BENZOYL PEROXIDE, >36-42% WITH 40% WATER	T		
94-36-0		BENZOYL PEROXIDE, >51-100%	T		
94-36-0		BENZOYL PEROXIDE, >52-62% AS A PASTE	T		
94-36-0		BENZOYL PEROXIDE, >77-94% WITH 6% WATER	T		
538-86-3		BENZYL METHYL ETHER	D		
	4-(BENZYL(METHYL) AMINO)3-ETHOXY-BENZENEDIAZONIUM ZINC CHLORIDE	T		
6921-34-2		BENZYL MAGNESIUM CHLORIDE	A	W	
13597-99-4		BERYLLIUM NITRATE	O		
77-73-6		BICYCLOPENTADIENE	D		
106-99-0		BIETHYLENE	D		
		BIPHENYL TRIOZONIDE	D		
12001-89-7		BIS (1,2,3,4,5,6-ETA)-(1-METHYLETHYL) BENZENE)-CHROMIUM	A	W	
312-30-1		BIS (4-FLUORO-3-NITROPHENYL) SULFONE	S		
12001-89-7		BIS (CUMENE) CHROMIUM	A	W	
12001-89-7		BIS (DI-CUMENE) CHROMIUM	A	W	
12001-89-7		BIS (ISOPROPYLBENZENE) CHROMIUM	A	W	
101-68-8		BIS(1,4-ISOCYANATOPHENYL)MEHTANE	W		
133-14-2		BIS(2,4-DICHLOROBENZOYL)-PEROXIDE, <=52% AS A PASTE	T		
108-60-1		BIS(2-CHLORO-1-METHYLETHYL)ETHER	D		
111-44-4		BIS(2-CHLOROETHYL)ETHER	D		
108-60-1		BIS-(2-CHLOROISOPROPYL)ETHER	D		
112-36-7		BIS(2-ETHOXYETHYL)ETHER	D		
111-96-6		BIS(2-METHOXYETHYL)ETHER	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
101-68-8		BIS(4-ISOCYANATOPHENYL)METHANE	W		
112-73-2		BIS(BUTOXYETHYL)ETHER	D		
111-44-4		BIS(CHLORO-2-ETHYL) OXIDE	D		
542-88-1		BIS(CHLOROMETHYL) ETHER	D		
998-00-5		BIS(DIISOBUTYLALUMINUM) OXIDE	A		
13826-66-9		BIS(NITRATO-O)OXOZIRCONIUM	O		
25155-25-3		BIS(TERT-BUTYLPEROXY) DIISOPROPYL BENZENE, >42-100%	T		
28930-30-5		BIS(TRINITROPHENYL)SULFIDE (DRY)	S		
77-73-6		BISCYCLOPENTADIENE	D		
10361-44-1		BISMUTH NITRATE	O		
10361-44-1		BISMUTH TERNITRATE	O		
10361-44-1		BISMUTH TRINITRATE	O		
106-99-0		BIVINYL	D		
		BLACK POWDER	S		
55-63-0		BLASTING GELATIN	S		
55-63-0		BLASTING OIL	S		
7440-66-6		BLUE POWDWE	W		
88-85-7		BNP (20:30)	S		
74-94-2		BORANE-DIMETHYL AMINE COMPLEX	W		
13292-87-0		BORANE-METHYLSULFIDE COMPLEX	W		
4856-95-5		BORANE-MORPHOLINE COMPLEX	W		
110-51-0		BORANE-PYRIDINE COMPLEX	W		
14044-65-6		BORANE-THF COMPLEX	W		
1722-26-5		BORANE-TRIETHYLAMINE COMPLEX	W		
75-22-9		BORANE-TRIMETHYLAMINE COMPLEX	W		
6569-51-3		BORAZINE	W		
6569-51-3		BORAZOLE	W		
121-43-7		BORESTER O	W		
121-43-7		BORIC ACID TRIMETHYL ESTER	W		
19287-45-7		BOROETHANE (POISON INHALATION HAZARD)	O	A	
10294-34-5		BORON CHLORIDE (POISON INHALATION HAZARD)	W		
7440-42-8		BORON DUST	A		
10294-34-5		BORON TRICHLORIDE (POISON INHALATION HAZARD)	W		
97-94-9		BORON TRIETHYL	A		
109-63-7		BORON TRIFLUORIDE DIETHYL ETHERATE	W		
353-42-4		BORON TRIFLUORIDE DIMETHYL ETHERATE	W		
109-63-7		BORON TRIFLUORIDE ETHERATE	W		
109-63-7		BORON TRIFLUORIDE ETHYL ETHER	W		
109-63-7		BORON TRIFLUORIDE-ETHER COMPLEX	W		
7789-38-0		BROMIC ACID SODIUM SALT	O		
7758-01-2		BROMIC ACID, POTASSIUM SALT	O		
13973-87-0		BROMINE AZIDE	S	T	

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure

O - Strong Oxidizing Materials

S - Shock, Friction, Static Charge

W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)

P - Pressure Release (for future use)

T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
7789-30-2		BROMINE PENTAFLUORIDE (POISON INHALATION HAZARD)	W		
7787-71-5		BROMINE TRIFLUORIDE (POISON INHALATION HAZARD)	W		
13465-73-1		BROMO SILANE	D		
	4-	BROMO-1,2-DINITROBENZENE	D		
585-79-5	1-	BROMO-3-NITROBENZENE	D		
101-55-3	1-	BROMO-4-PHENOXYBENZENE	D		
598-21-0		BROMOACETYL BROMIDE	W		
2218-09-8		BROMOACETYL CHLORIDE	W		
101-55-3		BROMODIPHENYL ETHER	D		
592-55-2		BROMOETHYL ETHYL ETHER	D		
101-55-3	4-	BROMOPHENYL PHENYL ETHER	D		
103-64-0		BROMOSTYRENE	D		
103-64-0		BROMOSTYROL	D		
106-99-0	1,3-	BUTADIENE	D		
106-99-0		BUTADIENE	D		
2082-81-7	1,4-	BUTANEDIOLDIACRYLATE	D		
6659-60-5		BUTANETRIOL TRINITRATE	D		
6659-60-5	1,2,4	BUTANETRIOL TRINITRATE	D		
88-85-7		BUTAPHENE	S		
78-94-4	3-	BUTEN-2-ONE	D		
689-97-4		BUTEN-3-YNE	D		
625-38-7	3-	BUTENOIC ACID	D		
1070-19-5	TERT-	BUTOXYCARBONYL AZIDE	S	T	
111-76-2	2-	BUTOXYETHANOL	D		
112-34-5	2-(2-	BUTOXYETHOXY)ETHANOL	D		
4435-53-4		BUTOXYL	D		
1634-04-4	TERT-	BUTOXYMETHANE	D		
124-17-4		BUTYL "CARBITOL" ACETATE	D		
0111-76-2		BUTYL "CELLOSOLVE" ACETATE	D		
141-32-2		BUTYL 2-PROPENOATE	D		
141-32-2	N-	BUTYL ACRYLATE	D		
1070-19-5	TERT-	BUTYL AZIDOFORMATE	S	T	
112-34-5		BUTYL CARBITOL	D		
111-76-2		BUTYL CELLOSOLVE	D		
	TERT-	BUTYL CUMYL PEROXIDE, <=42%	T		
3457-61-2	T-	BUTYL CUMYL PEROXIDE, >42-100%	T		
112-73-2		BUTYL DIGLYME	D		
142-96-1		BUTYL ETHER	D		
2426-08-6	N-	BUTYL GLYCIDYL ETHER	D		
75-91-2	T-	BUTYL HYDROPEROXIDE, <=72% WITH >=28% WATER	T		
75-91-2	T-	BUTYL HYDROPEROXIDE, <=79% WITH >14% WATER	T		
75-91-2	TERT-	BUTYL HYDROPEROXIDE, <=80%	T		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
75-91-2	TERT-	BUTYL HYDROPEROXIDE, <82% WITH DI-TERT-BUTYL PEROXIDE, >9%	T		
75-91-2	TERT	BUTYL HYDROPEROXIDE, >79-90% WITH >=10% WATER	T		
75-91-2	TERT-	BUTYL HYDROPEROXIDE, >90%	T	S	
507-40-4	T-	BUTYL HYPOCHLORITE	A		
	TERT	BUTYL HYPOCHLORITE	A		
109-72-8	N-	BUTYL LITHIUM	A	W	
594-19-4	TERT	BUTYL LITHIUM	A	W	
598-30-1	SEC-	BUTYL LITHIUM (IN SOLVENT)	A	W	
585-07-9	TERT	BUTYL METHACRYLATE	D		
97-88-1	N-	BUTYL METHACRYLATE (DOMESTIC SHIPMENTS)	D		
97-88-1	N-	BUTYL METHACRYLATE (INTERNATIONAL SHIPMENTS)	D		
1634-04-4	TERT-	BUTYL METHYL ETHER	D		
	TERT-	BUTYL MONOPEROXYMALEATE, <=42% AS A PASTE	T		
1931-62-2	TERT	BUTYL MONOPEROXYMALEATE, <=52% AS A PASTE	T		
1931-62-2	TERT	BUTYL MONOPEROXYMALEATE, <=52% LIQUID	T		
	TERT-	BUTYL MONOPEROXYMALEATE, <=52% SOLID	T		
1931-62-2	TERT	BUTYL MONOPEROXYMALEATE, >52-100%	T		
	TERT	BUTYL MONOPEROXYPHTHALATE, <=100%	T		
928-45-0	N-	BUTYL NITRATE	O	S	
	TERT-	BUTYL PEROCTOATE, <=32%	T		
3006-82-4	TERT-	BUTYL PEROCTOATE, <=52% LIQUID	T		
	TERT-	BUTYL PEROCTOATE, <=52% SOLID	T		
3006-82-4	TERT-	BUTYL PEROCTOATE, >52-100%	T		
	T-	BUTYL PEROXIDE, <=52%	T		
110-05-4	T-	BUTYL PEROXIDE, >32-100%	T		
2372-21-6	TERT	BUTYL PEROXY ISOPROPYLCARBONATE, <=77%	T		
3006-82-4	TERT	BUTYL PEROXY-2-ETHYLHEXANOATE, <=12% AND 2,2-DI(TERT-BUTYLPEROXY) BUTANE, <=14%	T		
3006-82-4	TERT	BUTYL PEROXY-2-ETHYLHEXANOATE, <=31% AND 2,2-DI(TERT-BUTYLPEROXY) BUTANE, <=36%	T		
	TERT-	BUTYL PEROXY-2-ETHYLHEXANOATE, <=32%	T		
	TERT-	BUTYL PEROXY-2-ETHYLHEXANOATE, <=52% SOLID	T		
3006-82-4	TERT	BUTYL PEROXY-2-ETHYLHEXANOATE, >32-52% LIQUID	T		
3006-82-4	TERT	BUTYL PEROXY-2-ETHYLHEXANOATE, >52-100%	T		
	TERT-	BUTYL PEROXY-2-ETHYLHEXYL CARBONATE, <=100%	T		
	TERT-	BUTYL PEROXY-2-METHYL BENZOATE, <=100%	T		
	TERT-	BUTYL PEROXY-3,5,5-TRIMETHYLHEXANOATE, <=32%	T		
	TERT-	BUTYL PEROXY-3,5,5-TRIMETHYLHEXANOATE, >32-100%	T		
	3-TERT-	BUTYL PEROXY-3-PHENYLPHTHALIDE, <=100%	T		
	TERT-	BUTYL PEROXYACETATE, <=22%	T		
	TERT-	BUTYL PEROXYACETATE, <=32%	T		
107-71-1	TERT	BUTYL PEROXYACETATE, >32-52%	T		
107-71-1	TERT	BUTYL PEROXYACETATE, >52-77%	T		
	T-	BUTYL PEROXYACETATE, >77%	T	S	

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure

O - Strong Oxidizing Materials

S - Shock, Friction, Static Charge

W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)

P - Pressure Release (for future use)

T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
	TERT-	BUTYL PEROXYBENZOATE, <=33% AND TERT-BUTYL PEROXYDIETHYLACETATE, <=33%	T		
614-45-9	TERT-	BUTYL PEROXYBENZOATE, <=52%	T		
614-45-9	TERT-	BUTYL PEROXYBENZOATE, >52-77%	T		
614-45-9	T-	BUTYL PEROXYBENZOATE, >77-100%	T		
	T-	BUTYL PEROXYBUTYL FUMARATE, <=52%	T		
	TERT-	BUTYL PEROXYCROTONATE, <=77%	T		
	N-	BUTYL PEROXYDICARBONATE, >52%	T	S	
	TERT	BUTYL PEROXYDIETHYLACETATE, <=100%	T		
	TERT	BUTYL PEROXYDIETHYLACETATE, <=33% AND TERT-BUTYL PEROXYBENZOATE, <=33%	T		
109-13-7	TERT	BUTYL PEROXYISOBUTYRATE, <=52%	T		
109-13-7	TERT	BUTYL PEROXYISOBUTYRATE, >52-77%	T		
109-13-7	TERT	BUTYL PEROXYISOBUTYRATE, >77%	T	S	
1931-62-2	TERT-	BUTYL PEROXYMALEIC ACID, <=52% LIQUID	T		
	TERT-	BUTYL PEROXYMALEIC ACID, <=52% SOLID	T		
	TERT-	BUTYL PEROXYMALEIC ACID, >=42% AS A PASTE	T		
1931-62-2	TERT-	BUTYL PEROXYMALEIC ACID, >=52% AS A PASTE	T		
1931-62-2	TERT-	BUTYL PEROXYMALEIC ACID, >52-100%	T		
	TERT-	BUTYL PEROXYNEODECANOATE, <=42% AS A STABLE DISPERSION IN WATER	T		
26748-41-4	TERT-	BUTYL PEROXYNEODECANOATE, <=77%	T		
26748-41-4	T-	BUTYL PEROXYNEODECANOATE, >77-100%	T		
	TERT-	BUTYL PEROXYNEOHEPTANOATE, <=77%	T		
	TERT-	BUTYL PEROXYPIVALATE, <=27%	T		
927-07-1	TERT-	BUTYL PEROXYPIVALATE, <=67%	T		
927-07-1	TERT	BUTYL PEROXYPIVALATE, >67-77%	T		
1126-79-0		BUTYL PHENYL ETHER	D		
111-34-2	N-	BUTYL VINYL ETHER	D		
81-15-2	5-TERT-	BUTYL-2,4,6-TRINITRO-M-XYLENE	S		
	N-	BUTYL-4,4-DI-(TERT-BUTYLPEROXY) VALERATE, <=42%	T		
995-33-5	N-	BUTYL-4,4-DI-(TERT-BUTYLPEROXY) VALERATE, <=52%	T		
995-33-5	N-	BUTYL-4,4-DI-(TERT-BUTYLPEROXY) VALERATE, >52-100%	T		
88-85-7	2-SEC	BUTYL-4,6-DINITROPHENOL	S		
3775-90-4	TERT	BUTYLAMINOETHYL METHACRYLATE	D		
4262-43-5	TERT-	BUTYLARSINE (POISON INHALATION HAZARD)	A		
2082-81-7		BUTYLENE DIMETHACRYLATE	D		
62202-86-2	N-	BUTYLETHYL MAGNESIUM	A	W	
693-04-9		BUTYLMAGNESIUM CHLORIDE	A	W	
	1-(2-	BUTYLPEROXY ISOPROPYL)-3-ISOPROPENYLBENZENE, <=42%	T		
	1-(2-	BUTYLPEROXY ISOPROPYL)-3-ISOPROPENYLBENZENE, <=77%	T		
	TERT-	BUTYLPEROXY STEARYL CARBONATE, <=100%	T		
2501-94-2	T-	BUTYLPHOSPHINE (POISON INHALATION HAZARD)	A		
110-65-6		BUTYNEDIOL	D		
94-36-0		BZW-70	T		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure

O - Strong Oxidizing Materials

S - Shock, Friction, Static Charge

W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)

P - Pressure Release (for future use)

T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

<i>Chemical CAS#</i>	<i>Prefix</i>	<i>Chemical Name</i>	<i>Reactive Chemical Stimulus 1</i>	<i>Reactive Chemical Stimulus 2</i>	<i>Reactive Chemical Stimulus 3</i>
88-89-1		C.I. 10305 (DRY)	S		
88-89-1		C.I.10305 (WET > 30% WATER)	S		
		CABAZIDE	D		
94-36-0		CADET BPO-70W	T		
94-36-0		CADET BPO-78W	T		
14518-94-6		CADMIUM BROMATE	O		
7790-81-0		CADMIUM IODATE	O		
10022-68-1		CADMIUM NITRATE	O		
12014-28-7		CADMIUM PHOSPHIDE	W		
94-36-0		CADOX 40E	T		
94-36-0		CADOX BFF-50	T		
94-36-0		CADOX BFF-60W	T		
94-36-0		CADOX BPO-40W	T		
94-36-0		CADOX BTW-40	T		
94-36-0		CADOX BTW-50	T		
94-36-0		CADOX BTW-55	T		
1338-23-4		CADOX F-85	T		
1338-23-4		CADOX L-30	T		
1338-23-4		CADOX L-50	T		
1338-23-4		CADOX M-30	T		
1338-23-4		CADOX M-50	T		
1338-23-4		CADOX MDA-30	T		
133-14-2		CADOX TDP	T		
133-14-2		CADOX TS	T		
133-14-2		CADOX TS-50S	T		
7440-70-2		CALCIUM	W		
75-20-7		CALCIUM ACETYLIDE	W		
6484-52-2		CALCIUM AMMONIUM NITRATE	O		
10102-75-7		CALCIUM BROMATE	O		
75-20-7		CALCIUM CARBIDE	W		
156-62-7		CALCIUM CARBIMIDE, NOT HYDRATED >0.1% CALCIUM CARBIDE	W		
10137-74-3		CALCIUM CHLORATE SOLUTION	O		
10137-74-3		CALCIUM CHLORATE, SOLID	O		
156-62-7		CALCIUM CYANAMIDE, NOT HYDRATED >0.1% CALCIUM CARBIDE	W		
		CALCIUM DITHIONITE	A		
7789-78-8		CALCIUM HYDRIDE	W		
		CALCIUM HYDROSULFITE	A		
7789-80-2		CALCIUM IODATE	O		
		CALCIUM MANGANESE SILICON	W		
10124-37-5		CALCIUM NITRATE	O		
13477-36-6		CALCIUM PERCHLORATE	O		
1305-99-3		CALCIUM PHOSPHIDE	W		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
12737-18-7		CALCIUM SILICIDE	W		
88-85-7		CALDON	S		
101-68-8		CARADATE 30	W		
107-13-1		CARBACRYL	D		
124-43-6		CARBAMIDE PEROXIDE	T		
420-04-2		CARBAMONITRILE	T		
88-89-1		CARBAZOTIC ACID (DRY)	S		
88-89-1		CARBAZOTIC ACID (WET >30% WATER)	S		
420-04-2		CARBIMIDE	T		
112-15-2		CARBITOL ACETATE	D		
74-90-8		CARBON HYDRIDE NITRIDE, ANHYDROUS, STABILIZED (PIH)	S		
140-88-5		CARBONYL ETHYLENE	D		
1189-71-5	N-	CARBONYLSULFAMYL CHLORIDE	W		
55-63-0		CARDAMIST	S		
88-85-7		CASWELL NO. 392DD	S		
26628-22-8		CASWELL NO. 744A	S	T	
7632-00-0		CASWELL NO. 782	O		
40487-42-1		CASWELL NO.454BB	S		
274-07-7		CATECHOLBORANE	W		
141-52-6		CAUSTIC ALCOHOL	W		
		CELLULOID, BLOCK, RODS, ROLLS, SHEETS, TUBES, ETC., EXCEPT SCRAP	S		
9004-70-0		CELLULOSE NITRATE (DRY)	S		
9004-70-0		CELLULOSE NITRATE (WET >25% WATER)	S		
20859-73-8		CELPHOS	W		
16774-21-3		CERIC AMMONIUM NITRATE	O		
7440-45-1		CERIUM METAL (TURNINGS OR POWDER)	W		
10294-41-4		CERIUM NITRATE, HEXAHYDRATE	O		
10294-41-4		CEROUS NITRATE, HEXAHYDRATE	O		
7440-46-2		CESIUM	W		
7789-18-6		CESIUM NITRATE	O		
		CESIUM PEROXIDE	W		
		CESIUM TETROXIDE	W		
88-85-7		CHEMOX (GENERAL;P.E.;	S		
111-44-4	2-	CHLORETHYL ETHER	D		
111-44-4		CHLOREX	D		
7790-93-4		CHLORIC ACID	O		
3811-04-9		CHLORIC ACID, POTASSIUM SALT	O		
3811-04-9		CHLORIC ACID, POTASSIUM SALT SOLUTION	O		
13453-30-0		CHLORIC ACID, THALLIUM SALT	O		
13973-88-1		CHLORINE AZIDE	D		
10049-04-4		CHLORINE DIOXIDE (NOT HYDRATED)	S		
7790-93-4		CHLORINE DIOXIDE HYDRATE FROZEN	O		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
7790-89-8		CHLORINE MONOFLUORIDE (POISON INHALATION HAZARD)	P	O	
10049-04-4		CHLORINE OXIDE	S		
10049-04-4		CHLORINE PEROXIDE	S		
7790-91-2		CHLORINE TRIFLUORIDE (POISON INHALATION HAZARD)	W	O	
10049-04-4		CHLORINE(IV)OXIDE	S		
1779-25-5		CHLORO BIS(2-METHYLPROPYL)-ALUMINUM	A		
28260-61-9	2-	CHLORO-1,3,5-TRINITROBENZENE	S		
97-00-7	1-	CHLORO-2,4,-DINITROBENZENE	S		
78-95-5	1-	CHLORO-2-PROPANONE, UNSTABILIZED	D		
78-95-5		CHLOROACETONE, UNSTABILIZED	D		
79-04-9		CHLOROACETYL CHLORIDE (POISON INHALATION HAZARD)	W		
920-37-6	2-	CHLOROACRYLONITRILE	D		
502-98-7		CHLOROAZODIN (SALTS OF)(DRY)	D		
557-98-2	2-	CHLOROBUTADIENE, INHIBITED	D		
96-10-6		CHLORODIETHYL ALUMINUM	A		
1779-25-5		CHLORODIISOBUTYLALUMINUM	A		
107-30-2		CHLORODIMETHYL ETHER (POISON INHALATION HAZARD)	D	W	
768-33-2		CHLORODIMETHYLPHENYLSILANE	A		
75-01-4		CHLOROETHENE	D		
110-75-8	2-	CHLOROETHOXY ETHENE	D		
110-75-8	2-	CHLOROETHOXYETHANE	D		
110-75-8	2-	CHLOROETHYL VINYL ETHER	D		
75-01-4		CHLOROETHYLENE	D		
101-38-2	4-	CHLOROIMINO-2,6-DICHLORO-2,5-CYCLOHEXADIENE-1-ONE	T		
107-30-2		CHLOROMETHOXYMETHANE (POISON INHALATION HAZARD)	D	W	
542-88-1		CHLOROMETHYL ETHER	D		
107-30-2		CHLOROMETHYLMETHYL ETHER (POISON INHALATION HAZARD)	D	W	
937-14-4	3-	CHLOROPEROXYBENZOIC ACID, <=57% WITH 40% WATER	T		
937-14-4	3-	CHLOROPEROXYBENZOIC ACID, <=77% WITH 17% WATER	T		
937-14-4	3-	CHLOROPEROXYBENZOIC ACID, >57-86%	T		
10049-04-4		CHLOROPEROXYL	S		
873-77-8		CHLOROPHENYLMAGNESIUM BROMIDE (IN SOLVENT)	W		
51833-36-4		CHLOROPHENYLMAGNESIUM CHLORIDE (IN SOLVENT)	W		
557-98-2		CHLOROPRENE, INHIBITED	D		
557-98-2	BETA-	CHLOROPRENE, UNINHIBITED	D		
1189-71-5		CHLOROSULFONYL ISOCYANATE	W		
75-77-4		CHLOROTRIMETHYL SILANE	W		
10049-04-4		CHLORYL RADICAL	S		
1333-82-0		CHROMIC ACID, SOLID	O		
1333-82-0		CHROMIC ANHYDRIDE, SOLID	O		
13548-38-4		CHROMIC NITRATE	O		
13007-92-6		CHROMIUM CARBONYL	S		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
13007-92-6		CHROMIUM HEXACARBONYL	S		
13548-38-4		CHROMIUM NITRATE	O		
		CHRYSAMMINIC ACID	D		
100-42-5		CINNAMENE, INHIBITED	D		
107-30-2		CMME (POISON INHALATION HAZARD)	D	W	
10026-22-9		COBALT (2) NITRATE HEXAHYDRATE	O		
10210-68-1		COBALT CARBONYL	A		
10026-22-9		COBALT NITRATE	O		
10210-68-1		COBALT OCTACARBONYL	A		
13478-33-6		COBALT PERCHLORATE	O	S	
10210-68-1		COBALT TETRACARBONYL	A		
10026-22-9		COBALTOUS NITRATE	O		
13478-33-6		COBALTOUS PERCHLORATE	O	S	
9004-70-0		COLLODION (NITROCELLULOSE IN ETHER & ALCOHOL)	P	S	
3251-23-8		COPPER (2) NITRATE	O		
19004-19-4		COPPER (2) NITRATE HEMIPENTAHYDRATE	O		
12540-13-3		COPPER ACETYLIDE	D		
		COPPER AMINE AZIDE	D		
		COPPER TETRAMINE NITRATE	D		
55-63-0		CORDITRINE	S		
13071-79-9		COUNTER	W		
602-99-3		CRESOLITE	S		
602-99-3		CRESYLITE	S		
20859-73-8		CSAWELL NO. 031	W		
98-82-8		CUMENE	D		
80-15-9		CUMENE HYDROPEROXIDE, <=90%	T		
		CUMENE HYDROPEROXIDE, >90-98%	T		
98-82-8		CUMOL	D		
80-15-9		CUMYL HYDROPEROXIDE, <=90%	T		
		CUMYL HYDROPEROXIDE, >90-98%	T		
		CUMYL PEROXYNEODECANOATE, <=52% AS A STABLE DISPERSION IN WATER	T		
		CUMYL PEROXYNEODECANOATE, <=77%	T		
		CUMYL PEROXYNEOHEPTANOATE, <=77%	T		
23383-59-7	ALPHA	CUMYL PEROXYPIVALATE, <=77%	T		
3251-23-8		CUPRIC (2) NITRATE	O		
156-62-7		CYANAMID	W		
420-04-2		CYANAMIDE	T		
156-62-7		CYANAMIDE, CALCIUM SALT (1:1)	W		
126-98-7	2-	CYANO-1-PROPENE	D		
420-04-2		CYANOAMINE	T		
107-13-1		CYANOETHENE	D		
7085-85-0	2-	CYANOETHYL ACRYLATE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
107-13-1		CYANOETHYLENE	D		
1071-22-3	2-	CYANOETHYLTRICHLOROSILANE	W		
420-04-2		CYANOGEN NITRIDE	T		
420-04-2		CYANOGENAMIDE	T		
126-98-7	2-	CYANOPROPENE	D		
126-98-7	2-	CYANOPROPENE-1	D		
7677-24-9		CYANOTRIMETHYLSILANE	W		
675-14-9		CYANURIC FLUORIDE	W		
		CYANURIC TRIAZIDE	D		
78-18-2		CYCLOHEXANONE PEROXIDE, <=72%	T		
78-18-2		CYCLOHEXANONE PEROXIDE, <=72% AS A PASTE	T		
78-18-2		CYCLOHEXANONE PEROXIDE, <=91%	T		
110-83-8		CYCLOHEXENE	D		
3173-53-3		CYCLOHEXYL ISOCYANATE (POISON INHALATION HAZARD)	W		
931-51-1		CYCLOHEXYL MAGNESIUM CHLORIDE (2.0M IN ETHER)	W		
131-89-5	2-	CYCLOHEXYL-4,6-DINITROPHENOL	S		
121-82-4		CYCLONITE (WET >15% WATER)	S		
78-18-2		CYCLONOX BT-50	T		
629-20-9	1357-	CYCLOOCTATETRAENE	D		
542-92-7	1,3-	CYCLOPENTADIENE	D		
77-73-6		CYCLOPENTADIENE DIMER	D		
77-73-6	1,3-	CYCLOPENTADIENE DIMER	D		
16733-97-4		CYCLOPENTADIENYL LITHIUM	W		
1284-72-6	BIS	CYCLOPENTADIENYL MAGNESIUM, SUBLIMED	W		
33240-34-5		CYCLOPENTYL MAGNESIUM BROMIDE (IN SOLVENT)	W		
32916-51-1		CYCLOPENTYL MAGNESIUM CHLORIDE (IN SOLVENT)	W		
2691-41-0		CYCLOTETRAMETHYLENE TETRANITRAMINE (DRY)	S		
2691-41-0		CYCLOTETRAMETHYLENE TETRANITRAMINE (WET >15% WATER)	S		
121-82-4		CYCLOTRIMETHYLENE TRINITRAMINE (WET >15% WATER)	S		
121-82-4		CYCLOTRIMETHYLENE TRINITRAMINE, DESENSITIZED	S		
156-62-7		CY-L 500	W		
131-17-9		DAP	D		
38078-09-0		DAST	A	W	
88-85-7		DBNF	S		
111-44-4		DCEE	D		
108-60-1		DCIP(NEMATOCIDE)	D		
77-73-6		DCPD	D		
87-31-0		DDNP (DRY)	D		
87-31-0		DDNP (WET >40% WATER)	S		
760-19-0		DEAB	A		
96-10-6		DEAC	A		
367-44-2		DEAF	A		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
2040-00-8		DEAI	A		
1586-92-1		DEAL-E	A		
871-27-2		DEAL-H	A		
17702-41-9		DECABORANE	A		
762-12-9		DECANOX-F	T		
10326-21-3		DE-FOL-ATE	O		
693-21-0		DEGN (DRY)	D		
693-21-0		DEGN (WET >25% WATER)	S		
534-52-1		DEGRASSAN	S		
534-52-1		DEKRYNIL	S		
1609-47-8		DEPC	W		
101-68-8		DESMODUR 44	W		
87413-09-0		DESS-MARTIN PERIODINANE	S	T	
534-52-1		DETAL	S		
20859-73-8		DETIA (EX-B; GAS EX-B)	W		
557-20-0		DEZ	A	W	
		DI(1-HYDROXY TETRAZOLE)(DRY)	D		
		DI-(1-HYDROXYCYCLOHEXYL)PEROXIDE, <=100%	T		
		DI(1-NAPHTHOYL)PEROXIDE	D		
1611-62-9		DI(2-ETHYLHEXYL)PEROXYDICARBONATE, <=52% AS A STABLE DISPERSION IN WATER	T		
1611-62-9		DI(2-ETHYLHEXYL)PEROXYDICARBONATE, <=77%	T		
1611-62-9		DI(2-ETHYLHEXYL)PEROXYDICARBONATE, >77-100%	T		
		DI-(2-METHYLBENZOYL)PEROXIDE, <=87% WITH 13% WATER	T		
		DI-(2-NEODECANOYLPEROXYISOPROPYL) BENZENE, <=52%	T		
41935-39-1		DI-(2-PHENOXYETHYL) PEROXYDICARBONATE, <=85% WITH 15% WATER	T		
41935-39-1		DI-(2-PHENOXYETHYL) PEROXYDICARBONATE, >85-100%	T		
25155-25-3		DI-(2-TERT-BUTYLPEROXYISOPROPYL)-BENZENE(S), >42-100%	T		
		DI-(3,5,5-TRIMETHYL-1,2-DIOXOLANYL-3) PEROXIDE, <=52% AS A PASTE	T		
		DI-(3,5,5-TRIMETHYLHEXANOYL) PEROXIDE, <=38%	T		
		DI-(3,5,5-TRIMETHYLHEXANOYL) PEROXIDE, <=52% AS A STABLE DISPERSION IN WATER	T		
3851-87-4		DI-(3,5,5-TRIMETHYLHEXANOYL) PEROXIDE, >38-82%	T		
	2,2-	DI-(4,4-DI(TERT-BUTYLPEROXY)CYCLOHEXYL)PROPANE, <=25%	T		
	2,2-	DI-(4,4-DI(TERT-BUTYLPEROXY)CYCLOHEXYL)PROPANE, <=42%	T		
	2,2-	DI-(4,4-DI(TERT-BUTYLPEROXY)CYCLOHEXYL)PROPANE, >42%	T	S	
		DI-(4-METHYLBENZOYL)PEROXIDE, <=52% AS A PASTE WITH SILICONE OIL	T		
15520-11-3		DI-(4-TERT-BUTYLCYCLOHEXYL) PEROXYDICARBONATE, <=100%	T		
15520-11-3		DI-(4-TERT-BUTYLCYCLOHEXYL) PEROXYDICARBONATE, <=42% AS A STABLE DISPERSION IN WATER	T		
		DI(BETA-NITROXYETHYL)AMMONIUM NITRATE	D		
111-90-0		DI(ETHYLENE GLYCOL) ETHYL ETHER	D		
	A,A'-	DI(NITROXY)METHYL ETHER	D		
	1,1-	DI-(TERT-AMYL PEROXY) CYCLOHEXANE, <=82%	T		
2167-23-9	2,2-	DI-(TERT-BUTYLPEROXY) BUTANE, <=52%	T		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
	2,2-	DI-(TERT-BUTYLPEROXY) BUTANE, >52%	T	S	
	1,1-	DI-(TERT-BUTYLPEROXY) CYCLOHEXANE, <=25%	T		
3006-86-8	1,1-	DI-(TERT-BUTYLPEROXY) CYCLOHEXANE, <=27%	T		
3006-86-8	1,1-	DI-(TERT-BUTYLPEROXY) CYCLOHEXANE, <=42%	T		
	1,1-	DI-(TERT-BUTYLPEROXY) CYCLOHEXANE, <=52%	T		
3006-86-8	1,1-	DI-(TERT-BUTYLPEROXY) CYCLOHEXANE, >52-80%	T		
3006-86-8	1,1-	DI-(TERT-BUTYLPEROXY) CYCLOHEXANE, >80-100%	T		
2155-71-7		DI-(TERT-BUTYLPEROXY) PHTHALATE, <=42%	T		
2155-71-7		DI-(TERT-BUTYLPEROXY) PHTHALATE, <=52% AS A PASTE	T		
2155-71-7		DI-(TERT-BUTYLPEROXY) PHTHALATE, >42-52%	T		
		DI-(TERT-BUTYLPEROXY) PHTHALATE, >52%	T	S	
	2,2-	DI-(TERT-BUTYLPEROXY) PROPANE, <=42%	T		
	2,2-	DI-(TERT-BUTYLPEROXY) PROPANE, <=52%	T		
6731-36-8	1,1-	DI-(TERT-BUTYLPEROXY)-3,3,5-TRIMETHYLCYCLOHEXANE, <=57% LIQUID	T		
6731-36-8	1,1-	DI-(TERT-BUTYLPEROXY)-3,3,5-TRIMETHYLCYCLOHEXANE, <=57% SOLID	T		
6731-36-8	1,1-	DI-(TERT-BUTYLPEROXY)-3,3,5-TRIMETHYLCYCLOHEXANE, >57-90%	T		
6731-36-8	1,1-	DI-(TERT-BUTYLPEROXY)-3,3,5-TRIMETHYLCYCLOHEXANE, >90-100%	T		
3006-82-4	2,2-	DI(TERT-BUTYLPEROXY)BUTANE, <=14% AND TERT-BUTYL PEROXY-2-ETHYLHEXANOATE, <=12%	T		
3006-82-4	2,2-	DI(TERT-BUTYLPEROXY)BUTANE, <=36% AND TERT-BUTYL PEROXY-2-ETHYLHEXANOATE, <=31%	T		
133-14-2		DI-2,4-DICHLOROBENZOYL PEROXIDE, <=52% AS A PASTE	T		
133-14-2		DI-2,4-DICHLOROBENZOYL PEROXIDE, <=77% WITH 23% WATER	T		
133-14-2		DI-2,4-DICHLOROBENZOYL PEROXIDE, >77%	T	S	
133-14-2		DI-4-CHLOROBENZOYL PEROXIDE, <=52% AS A PASTE	T		
133-14-2		DI-4-CHLOROBENZOYL PEROXIDE, <=77%	T		
		DIACETONE ALCOHOL PEROXIDES, <=57%	T		
		DIACETONE ALCOHOL PEROXIDES, >57%	T	S	
110-22-5		DIACETYL PEROXIDE, <=27%	T		
110-22-5		DIACETYL PEROXIDE, SOLID, OR MORE THAN 27% IN SOLUTION	T	S	
557-40-4		DIALLYL ETHER	D		
131-17-9		DIALLYL PHTHALATE	D		
302-01-2		DIAMINE, ANHYDROUS	S		
2294-47-5	P-	DIAZIDOBENZENE	D		
629-13-0	1,2-	DIAZIDOETHANE	D		
334-88-3		DIAZIRINE	D		
87-31-0	2-	DIAZO-4,6-DINITROBENZENE-1-OXIDE (DRY)	D		
136-35-6		DIAZOAMINOBENZENE	S		
	1,1'-	DIAZOAMINONAPHTHALENE	D		
		DIAZOAMINOTETRAZOLE (DRY)	D		
87-31-0		DIAZODINITROPHENOL (DRY)	D		
87-31-0		DIAZODINITROPHENOL (WET >40% WATER)	S		
883-40-9		DIAZODIPHENYL METHANE	D		
87-31-0		DIAZOL (DRY)	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
334-88-3		DIAZOMETHANE	D		
334-88-3		DIAZONIUM METHYLIDE	D		
		DIAZONIUM NITRATES (DRY)	D		
		DIAZONIUM PERCHLORATES (DRY)	D		
	1,3-	DIAZOPROPANE	D		
7632-00-0		DIAZOTIZING SALTS	O		
1779-25-5		DIBAC	A		
15769-72-9		DIBAL-E	A		
1191-15-7		DIBAL-H	A		
998-00-5		DIBAL-O	A		
94-36-0		DIBENZOYL PEROXIDE, <=52% AS A PASTE	T		
94-36-0		DIBENZOYL PEROXIDE, <=56.5% AS A PASTE WITH 15% WATER	T		
94-36-0		DIBENZOYL PEROXIDE, <=62% WITH 10% WATER	T		
94-36-0		DIBENZOYL PEROXIDE, <=77% WITH 23% WATER	T		
94-36-0		DIBENZOYL PEROXIDE, >35-52%	T		
94-36-0		DIBENZOYL PEROXIDE, >36-42%	T		
94-36-0		DIBENZOYL PEROXIDE, >36-42% WITH 40% WATER	T		
94-36-0		DIBENZOYL PEROXIDE, >51-100%	T		
94-36-0		DIBENZOYL PEROXIDE, >52-62% AS A PASTE	T		
94-36-0		DIBENZOYL PEROXIDE, >77-94% WITH 6% WATER	T		
2144-45-8		DIBENZYL PEROXYDICARBONATE, <=87% WITH 13% WATER	T		
		DIBENZYL PEROXYDICARBONATE, >87%	T	S	
19287-45-7		DIBORANE (POISON INHALATION HAZARD)	O	A	
19287-45-7		DIBORANE MIXTURES (POISON INHALATION HAZARD)	A	O	
19287-45-7		DIBORON HEXAHYDRIDE (POISON INHALATION HAZARD)	O	A	
537-45-1	2,6-	DIBROMO-4-(CHLOROIMINO)-2,5-CYCLOHEXADIEN-1-ONE	T		
624-61-3		DIBROMOACETYLENE	D		
624-61-3		DIBROMOMETHYNE	D		
537-45-1	2,6-	DIBROMO-N-CHLORO-P-BENZOQUINONEIMINE	T		
537-45-1	2,6-	DIBROMOQUINONE CHLORIMIDE	T		
1191-15-7		DIBUTYL ALUMINUM HYDRIDE	A		
112-73-2		DIBUTYL CARBITOL	D		
142-96-1	N-	DIBUTYL ETHER	D		
1191-47-5		DIBUTYL MAGNESIUM	A	W	
22673-19-4		DIBUTYLTIN ACETYLACETONATE	W		
1609-47-8		DICARBONIC ACID DIETHYL ESTER	W		
12078-23-8		DICARBONYL CYCLOPENTADIENYL COBALT	A	W	
		DICETYL PEROXYDICARBONATE, <=42% AS A STABLE DISPERSION IN WATER	T		
		DICETYL PEROXYDICARBONATE, <=100%	T		
502-98-7	N,N'	DICHLORAZODICARBONAMIDINE(SALTS OF)(DRY)	D		
111-44-4	1,5-	DICHLORO-3-OXAPENTANE	D		
7572-29-4		DICHLOROACETYLENE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
502-98-7		DICHLOROAZODICARBONAMIDINE	D		
111-44-4	2,2-	DICHLORODIETHYL ETHER	D		
108-60-1	2,2-	DICHLORODIISOPROPYL ETHER	D		
542-88-1		DICHLORODIMETHYL ETHER	D		
4885-02-3	1,1-	DICHLORODIMETHYL ETHER	D		
75-78-5		DICHLORODIMETHYLSILANE	A	W	
75-78-5		DICHLORODIMETHYLSILICON	A	W	
75-35-4	1,1-	DICHLOROETHENE, INHIBITED	D		
111-44-4		DICHLOROETHER	D		
111-44-4	SYM-	DICHLOROETHYL ETHER	D		
111-44-4	2,2-	DICHLOROETHYL ETHER	D		
111-44-4		DICHLOROETHYL OXIDE	D		
75-35-4	1,1-	DICHLOROETHYLENE, INHIBITED	D		
7572-29-4		DICHLOROETHYNE	D		
108-60-1		DICHLOROISOPROPYL ETHER	D		
542-88-1	SYM-	DICHLOROMETHYL ETHER	D		
4885-02-3		DICHLOROMETHYL METHYL ETHER	D		
75-54-7		DICHLOROMETHYLSILANE	W		
124-70-9		DICHLOROMETHYLVINYLSILANE	W		
101-38-2	2,6-	DICHLOROQUINONE-4-CHLOROIMIDE	T		
28469-92-3	2,6-	DICHLOROSTYRENE	D		
		DICHLOROVINYLBICHLOROARSINE	D		
10210-68-1		DICOBALT CARBONYL	A		
12001-89-7		DICUMENE CHROMIUM	A	W	
12001-89-7		DICUMENYL CHROMIUM	A	W	
		DICUMYL PEROXIDE, >52-100%	T		
80-43-3		DICUMYL PEROXIDE, >52-100%	T		
80-43-3		DICUP	T		
80-43-3		DICUP R	T		
80-43-3		DICUP T	T		
		DICYCLOHEXYL PEROXYDICARBONATE, <=91% WITH 9% WATER	T		
		DICYCLOHEXYL PEROXYDICARBONATE, >91-100%	T		
77-73-6		DICYCLOPENTADIENE	D		
762-12-9		DIDECANOYL PEROXIDE, <=100%	T		
2456-28-2		DIDECYL ETHER	D		
105-74-8		DIDODECANOYL PEROXIDE, <=100%	T		
105-74-8		DIDODECANOYL PEROXIDE, <=42% AS A STABLE DISPERSION IN WATER	T		
134191-62-1		DIDYMIUM NITRATE	O		
		DIETHANOL NITROSAMINE DINITRATE	D		
	2,5-	DIETHOXY-4-MORPHOLINOBENZENE DIAZONIUM ZINC CHLORIDE	T		
105-57-7	1,1-	DIETHOXYETHANE	D		
629-14-1	1,2-	DIETHOXYETHANE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

<i>Chemical CAS#</i>	<i>Prefix</i>	<i>Chemical Name</i>	<i>Reactive Chemical Stimulus 1</i>	<i>Reactive Chemical Stimulus 2</i>	<i>Reactive Chemical Stimulus 3</i>
126-84-1	2,2-	DIETHOXYPROPANE	D		
105-57-7		DIETHYL ACETAL	D		
760-19-0		DIETHYL ALUMINUM BROMIDE	A		
96-10-6		DIETHYL ALUMINUM CHLORIDE	A		
5804-85-3		DIETHYL ALUMINUM CYANIDE (POISON INHALATION HAZARD)	W		
1586-92-1		DIETHYL ALUMINUM ETHOXIDE	A		
871-27-2		DIETHYL ALUMINUM HYDRIDE	A		
38078-09-0		DIETHYL AMINOSULFUR TRIFLUORIDE	A	W	
112-36-7		DIETHYL CARBITOL	D		
1719-53-5		DIETHYL DICHLOROSILANE	W		
60-29-7		DIETHYL ETHER	D		
557-18-6		DIETHYL MAGNESIUM	A	W	
60-29-7		DIETHYL OXIDE	D		
		DIETHYL PEROXYDICARBONATE MORE THAN 27% IN SOLUTION	T	S	
14666-78-5		DIETHYL PEROXYDICARBONATE, <=27%	T		
1609-47-8		DIETHYL PYROCARBONATE	W		
627-53-2		DIETHYL SELENIDE	A	W	
627-53-2		DIETHYL SELENIUM	A	W	
627-54-3		DIETHYL TELLURIDE	A	W	
557-20-0		DIETHYL ZINC	A	W	
367-44-2		DIETHYLALUMINUM FLUORIDE	A		
2040-00-8		DIETHYLALUMINUM IODIDE	A		
		DIETHYLALUMINUM OXIDE	A	W	
692-42-2		DIETHYLARSINE	A		
542-63-2		DIETHYLBERYLLIUM	A	W	
123-91-1	1,4-	DIETHYLENE DIOXIDE	D		
123-91-1		DIETHYLENE DIOXIDE	D		
123-91-1		DIETHYLENE ETHER	D		
112-34-5		DIETHYLENE GLYCOL BUTYL ETHER	D		
112-73-2		DIETHYLENE GLYCOL DIBUTYL ETHER			D
111-44-4		DIETHYLENE GLYCOL DICHLORIDE	D		
111-96-6		DIETHYLENE GLYCOL DIMETHYL ETHER	D		
693-21-0		DIETHYLENE GLYCOL DINITRATE (DRY)	D		
693-21-0		DIETHYLENE GLYCOL DINITRATE (WET >25% WATER)	S		
112-34-5		DIETHYLENE GLYCOL MONOBUTYL ETHER	D		
124-17-4		DIETHYLENE GLYCOL MONOBUTYL ETHER ACETATE	D		
111-90-0		DIETHYLENE GLYCOL MONOETHYL ETHER	D		
112-15-2		DIETHYLENE GLYCOL MONOETHYL ETHER ACETATE			D
112-59-4		DIETHYLENE GLYCOL MONOHEXYL ETHER			D
111-77-3		DIETHYLENE GLYCOL MONOMETHYL ETHER	D		
123-91-1		DIETHYLENE OXIDE	D		
26645-10-3		DIETHYLGOLD BROMIDE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
54505-72-5		DIETHYLMALONYL DICHLORIDE	W	A	
327-92-4	1,5-	DIFLUORO-2,4-DINITROBENZENE	S		
312-30-1	P,P'-	DIFLUORO-M,M'-DINITROPHENYLSULFONE	S		
111-96-6		DIGLYCOL METHYL ETHER	D		
124-17-4		DIGLYCOL MONOBUTYL ETHER ACETATE	D		
693-21-0		DIGLYCOL NITRATE (DRY)	D		
693-21-0		DIGLYCOL NITRATE (WET >25% WATER)	S		
111-96-6		DIGLYME	D		
82-71-3	2,4-	DIHIDROXY-1,3,5-TRINITROBENZENE	S		
112-58-3		DIHEXYL ETHER	D		
1708-29-8	2,5-	DIHYDROFURAN	D		
	2,2-	DIHYDROPEROXYPROPANE, <=27%	T		
	1,8-	DIHYDROXY-2,4,5,7-TETRANITROANTHRAQUINONE(CHRYSAMMINIC ACID)	D		
74-39-5	2,4-	DIHYDROXY-4'-NITROAZOBENZENE	S		
624-74-8		DIIDOACETYLENE	D		
624-74-8		DIIDOETHYNE	D		
544-01-4		DIISOAMYL ETHER	D		
1779-25-5		DIISOBUTYL ALUMINUM CHLORIDE	A		
1191-15-7		DIISOBUTYL ALUMINUM HYDRIDE	A		
		DIISOBUTYL LITHIUM	A		
15769-72-9		DIISOBUTYLALUMINUM ETHOXIDE	A		
1779-25-5		DIISOBUTYLCHLOROALUMINUM	A		
3437-84-1		DIISOBUTYRYL PEROXIDE, <=32%	T		
3437-84-1		DIISOBUTYRYL PEROXIDE, >32-52%	T		
101-68-8	4,4-(P,P)-	DIISOCYANATODIPHENYLMETHANE	W		
		DIISONONANOYL PEROXIDE, <=38%	T		
		DIISONONANOYL PEROXIDE, <=52% AS A STABLE DISPERSION IN WATER	T		
3851-87-4		DIISONONANOYL PEROXIDE, >38-82%	T		
544-01-4		DIISOPENTYL ETHER	D		
108-20-3		DIISOPROPYL ETHER	D		
		DIISOPROPYL LITHIUM AMIDE	A	W	
108-20-3		DIISOPROPYL OXIDE	D		
105-64-6		DIISOPROPYL PEROXYDICARBONATE, <=52%	T		
105-64-6		DIISOPROPYL PEROXYDICARBONATE, >52-100%	T		
		DI-ISOPROPYLBENZENE DIHYDROPEROXIDE, <=82%	T		
		DIISOPROPYLCUMYL HYDROPEROXIDE, >72%	T	S	
		DIISOTRIDECYL PEROXYDICARBONATE, <=100%	T		
674-82-8		DIKETENE,INHIBITED (POISON INHALATION HAZARD)	D		
15825-70-4		DILANGIL	S		
105-74-8		DILAUYOYL PEROXIDE, <=100%	T		
105-74-8		DILAUYOYL PEROXIDE, <=42% AS A STABLE DISPERSION IN WATER	T		
534-52-1		DILLEX	S		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
10170-69-1		DIMANGANESE DECACARBONYL	A		
57-14-7		DIMAZIN	S		
57-14-7		DIMAZINE	S		
151-10-0	1,3-	DIMETHOXYBENZENE			D
91-16-7	1,2-	DIMETHOXYBENZENE			D
110-71-4	1,2-	DIMETHOXYETHANE	D		
109-87-5		DIMETHOXYMETHANE	D		
696-59-3	2,5-	DIMETHOXYTetrahydrofuran			D
506-82-1		DIMETHYL CADMIUM	A	W	
25136-55-4		DIMETHYL DIOXANE			D
20334-43-4		DIMETHYL DITELLURIDE	A	W	
115-10-6		DIMETHYL ETHER	D		
151-10-0		DIMETHYL RESORCINOL			D
593-80-6		DIMETHYL TELLURIDE	A	W	
544-97-8		DIMETHYL ZINC	A	W	
	2,5-	DIMETHYL-2,5-DI-(2-ETHYLHEXANOYLPEROXY)HEXANE, <=100%	T		
	2,5-	DIMETHYL-2,5-DI-(3,5,5-TRIMETHYLHEXANOYLPEROXY)HEXANE, <=77%	T		
2618-77-1	2,5-	DIMETHYL-2,5-DI-(BENZOYLPEROXY)HEXANE, <=82%	T		
2618-77-1	2,5-	DIMETHYL-2,5-DI-(BENZOYLPEROXY)HEXANE, <=82% WITH 18% WATER	T		
2618-77-1	2,5-	DIMETHYL-2,5-DI-(BENZOYLPEROXY)HEXANE, >82-100%	T		
	2,5-	DIMETHYL-2,5-DI-(TERT-BUTYLPEROXY)HEXANE, <=47% AS A PASTE	T		
78-63-7	2,5-	DIMETHYL-2,5-DI-(TERT-BUTYLPEROXY)HEXANE, <=52%	T		
78-63-7	2,5-	DIMETHYL-2,5-DI-(TERT-BUTYLPEROXY)HEXANE, >52-100%	T		
1068-27-5	2,5-	DIMETHYL-2,5-DI-(TERT-BUTYLPEROXY)HEXYNE-3, <=52%	T		
1068-27-5	2,5-	DIMETHYL-2,5-DI-(TERT-BUTYLPEROXY)HEXYNE-3, >52-86%	T		
	2,5-	DIMETHYL-2,5-DI-(TERT-BUTYLPEROXY)HEXYNE-3, >87-100%	T		
	2,5-	DIMETHYL-2,5-DIHYDROPEROXY HEXANE, >82%	T	S	
3025-88-5	2,5-	DIMETHYL-2,5-DIHYDROPEROXYHEXANE, <=82% WITH 18% WATER	T		
762-42-5		DIMETHYL-2-BUTYNEOATE	W		
	1,1-	DIMETHYL-3-HYDROXYBUTYLPEROXYNEOHEPTANOATE, <=52%	T		
762-42-5		DIMETHYLACETYLENE DICARBOXYLATE	W		
2680-03-7	N,N-	DIMETHYLACRYLAMIDE	D		
1184-58-3		DIMETHYLALUMINUM CHLORIDE	A	W	
74-94-2		DIMETHYLAMINE BORANE	W		
	4-	DIMETHYLAMINO-6-(2-DIMETHYLAMINOETHOXY) TOLUENE-2-DIAZONIUM ZINC CHLORIDE	T		
2867-47-2		DIMETHYLAMINOETHYL METHACRYLATE	D		
107-30-2		DIMETHYLCHLOROETHER (POISON INHALATION HAZARD)	D	W	
75-78-5		DIMETHYLDICHLOROSILANE	A	W	
151-56-4		DIMETHYLENIMINE, INHIBITED (POISON INHALATION HAZARD)	D		
1634-04-4	1,1-	DIMETHYLETHYL METHYL ETHER	D		
13071-79-9	S-{{(1,1-	DIMETHYLETHYL} THIO}METHYL} O,O-DIETHYL PHOSPHORODITHIOATE	W		
625-86-5		DIMETHYLFURAN	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
3025-88-5		DIMETHYLHEXANE DIHYDROPEROXIDE (DRY)	T	S	
57-14-7	N,N	DIMETHYLHYDRAZINE	S		
57-14-7	ASYM-	DIMETHYLHYDRAZINE	S		
540-73-8	1,2-	DIMETHYLHYDRAZINE, SYMMETRICAL (POISON INHALATION HAZARD)	S		
57-14-7		DIMETHYLHYDRAZINE, UNSYMMETRICAL (POISON INHALATION HAZARD) 1,1	S		
676-59-5		DIMETHYLPHOSPHINE	A		
13292-87-0		DIMETHYLSULFIDE BORANE COMPLEX	W		
		DIMYRISTYL ETHER	D		
		DIMYRISTYL PEROXYDICARBONATE, <=100%	T		
		DIMYRISTYL PEROXYDICARBONATE, <=42% AS A STABLE DISPERSION IN WATER	T		
16215-49-9		DI-N-BUTYL PEROXYDICARBONATE, <=27%	T		
		DI-N-BUTYL PEROXYDICARBONATE, <=42% AS A STABLE DISPERSION IN WATER (FROZEN)	T		
16215-49-9		DI-N-BUTYL PEROXYDICARBONATE, >27-52%	T		
16215-49-9		DI-N-BUTYL PEROXYDICARBONATE, >52%	T	S	
3537-86-8		DI-N-BUTYLALUMINUM CHLORIDE	A		
		DI-N-HEXYLMAGNESIUM	A		
88-85-7		DINITRALL	S		
	1,4-	DINITRO-1,1,4,4-TETRAMETHYLOLBUTANETETRANITRATE(DRY)	D		
87-31-0	5,7-	DINITRO-1,2,3-BENZOXADIAZOLE (DRY)	D		
	2,4-	DINITRO-1,3,5-TRIMETHYLBENZENE	D		
605-69-6	2,4-	DINITRO-1-NAPHTHOL	S		
88-85-7	4,6-	DINITRO-2-(1-METHYL-N-PROPYL)PHENOL	S		
534-52-1	3,5-	DINITRO-2-HYDROXYTOLUENE	S		
534-52-1	4,6-	DINITRO-2-METHYLPHENOL	S		
88-85-7		DINITRO-3	S		
	1,3-	DINITRO-4,5-DINITROBENZENE	D		
	1,3-	DINITRO-5,5-DIMETHYLHYDANTOIN	D		
367-81-7	2,4-	DINITRO-5-FLUOROANILINE	S		
88-85-7	2,4-	DINITRO-6-(1-METHYLPROPYL)PHENOL	S		
534-52-1	2,4-	DINITRO-6-METHYLPHENOL	S		
88-85-7	2,4-	DINITRO-6-SEC-BUTYLPHENOL	S		
		DINITRO-7,8-DIMETHYLGLYCOURIL(DRY)	D		
96-91-3		DINITROAMINOPHENOL (WET)	S		
97-02-9	2,4-	DINITROANILINE	S		
97-02-9	2,4-	DINITROBENZENAMINE	S		
100-25-4	P-	DINITROBENZENE	S		
100-25-4	1,4-	DINITROBENZENE	S		
99-65-0	M-	DINITROBENZENE	S		
99-65-0	1,3-	DINITROBENZENE	S		
528-29-0	O-	DINITROBENZENE	S		
528-29-0	1,2-	DINITROBENZENE	S		
89-02-1	2,4-	DINITROBENZENE SULFONIC ACID, 2-HYDRATE	S		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure

O - Strong Oxidizing Materials

S - Shock, Friction, Static Charge

W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)

P - Pressure Release (for future use)

T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
885-62-1	2,4-	DINITROBENZENE SULFONIC ACID, SODIUM SALT	S		
99-34-3	3,5-	DINITROBENZOIC ACID	S		
99-33-2	3,5-	DINITROBENZOYL CHLORIDE	S		
88-85-7		DINITROBUTYLPHENOL	S		
97-00-7		DINITROCHLOROBENZENE	S		
534-52-1		DINITROCRE SOL	S		
131-89-5		DINITROCYCLOHEXYLPHENOL	S		
534-52-1		DINITRODENDTROXAL	S		
	1,2-	DINITROETHANE	D		
	1,1-	DINITROETHANE(DRY)	D		
5405-53-8	2,7-	DINITROFLUORENE	S		
70-34-8	2,4-	DINITROFLUOROBENZENE	S		
10036-47-2		DINITROGEN TETRAFLUORIDE (POISON INHALATION HAZARD)	S	T	
693-21-0		DINITROGLYCOL (DRY)	D		
693-21-0		DINITROGLYCOL (WET >25% WATER)	S		
534-52-1		DINITROL	S		
625-76-3		DINITROMETHANE	D		
605-71-0	1,5-	DINITRONAPHTHALENE	S		
606-37-1	1,3-	DINITRONAPHTHALENE	S		
602-38-0	1,8-	DINITRONAPHTHALENE	S		
534-52-1	4,6-	DINITRO-O-CRESOL	S		
534-52-1		DINITRO-O-CRESOL	S		
534-52-1	3,5-	DINITRO-O-CRESOL	S		
131-89-5		DINITRO-ORTHO-CYCLOHEXYLPHENOL	S		
88-85-7		DINITRO-ORTHO-SEC-BUTYL-PHENOL	S		
88-85-7	4,6-	DINITRO-O-SEC-BUTYLPHENOL	S		
	3,4-	DINITRO-O-XYLENE	S		
609-93-8	2,6-	DINITRO-P-CRESOL	S		
51-28-5	2,4-	DINITROPHENOL (DRY)	S		
51-28-5	ALPHA	DINITROPHENOL (DRY)	S		
329-71-5	2,5-	DINITROPHENOL (DRY)	S		
51-28-5	2,4-	DINITROPHENOL (WET >15% WATER)	S		
329-71-5	2,5-	DINITROPHENOL (WET >15% WATER)	S		
25550-58-7		DINITROPHENOL SOLUTIONS	S		
119-26-6	2,4-	DINITROPHENYLHYDRAZINE (WET)	S		
		DINITROPROPYLENEGLYCOL	D		
	4,6-	DINITRORESORCINOL (HEAVY METAL SALTS OF) (DRY)	D		
35860-51-6	2,4-	DINITRORESORCINOL (WET)	S		
	2,4-	DINITRORESORCINOL(HEAVY METAL SALTS OF)(DRY)	D		
	3,5-	DINITROSALICYLIC ACID (LEAD SALT) (DRY)	D		
105-11-3		DINITROSOBENZENE	S		
		DINITROSOBENZYLAMIDE AND SALTS OF (DRY)	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
133-55-1	N,N'	DINITROSO-N,N'-DIMETHYL TEREPHTHALAMIDE (<72% AS A PASTE)	T		
101-25-7	N,N'	DINITROSOPENTAMETHYLENETETRAMINE, <=82%	T		
	2,2-	DINITROSTILBENE	D		
618-85-9	3,5-	DINITROTOLUENE	S		
610-39-9	3,4-	DINITROTOLUENE	S		
121-14-2	2,4-	DINITROTOLUENE	S		
606-20-2	2,6-	DINITROTOLUENE	S		
	1,9-	DINITROXPENTAMETHYLENE-2,4,6,8-TETRAMINE (DRY)	D		
		DI-N-NONANOYL PEROXIDE, <=100%	T		
534-52-1		DINOC	S		
		DI-N-OCTANOYL PEROXIDE, <=100%	T		
7585-14-0		DI-N-OCTYLALUMINUM IODIDE	A		
51-28-5		DINOFAN (DRY)	S		
87-31-0		DINOL (DRY)	D		
88-85-7		DINOSEB	S		
16066-38-9		DI-N-PROPYL PEROXYDICARBONATE, <=100%	T		
3710-19-8		DI-N-PROPYLALUMINUM CHLORIDE	A	W	
534-52-1		DINURANIA	S		
123-91-1	1,4-	DIOXACYCLOHEXANE	D		
123-91-1		DIOXAN	D		
123-91-1	1,4-	DIOXAN	D		
123-91-1	1,4-	DIOXANE	D		
123-91-1		DIOXANE	D		
123-91-1	P-	DIOXANE	D		
123-91-1	1,4-	DIOXIN, TETRAHYDRO-	D		
123-91-1		DIOXYETHYLENE ETHER	D		
108-20-3		DIPE	D		
		DIPEROXY AZELAIC ACID, <=27%	T		
		DIPEROXY DODECANE DIACID, >13-42%	T		
4129-17-3		DIPHENYL PHOSPHINIC AZIDE	W		
4129-17-3		DIPHENYL PHOSPHINYL AZIDE	W		
1898-66-4	2,2-	DIPHENYL-1-(2,4,6-TRINITROPHENYL)HYDRAZYL	S		
1898-66-4	2,2-	DIPHENYL-1-PICRYLHYDRAZYL HYDRATE	S		
1707-75-1	1,1-	DIPHENYL-2-PICRYLHYDRAZINE	S		
101-68-8		DIPHENYLMETHANE 4,4-DIISOCYANATE	W		
101-68-8		DIPHENYLMETHANE DIISOCYANATE	W		
136-35-6	1,3-	DIPHENYLTRIAZENE	S		
28930-30-5		DIPICRYL SULFIDE (DRY)	S		
28930-30-5		DIPICRYL SULFIDE (WET >10% WATER)	S		
131-73-7		DIPICRYLAMINE (2,2,4,4,6,6)	S		
		DIPROPIONYL PEROXIDE, <=27%	T		
		DIPROPIONYL PEROXIDE, >27%	T	S	

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
111-43-3		DIPROPYL ETHER	D		
2036-15-9		DIPROPYLALUMINUM HYDRIDE	A	W	
19910-65-7		DI-SEC-BUTYL PEROXYDICARBONATE, <=52%	T		
19910-65-7		DI-SEC-BUTYL PEROXYDICARBONATE, >52-100%	T		
1313-59-3		DISODIUM MONOXIDE	W		
59733-73-2		DISODIUM TETRACARBONYLFERRATE	A		
		DISTEARYL PEROXYDICARBONATE, <=87%	T		
123-23-9		DISUCCINIC ACID PEROXIDE, <=72% WITH 28% WATER	T		
123-23-9		DISUCCINIC ACID PEROXIDE, >72-100%	T		
7791-27-7		DISULFURYL CHLORIDE	W		
13170-23-5		DI-T-BUTOXYDIACETOXYSILANE	W		
		DI-TERT-AMYL PEROXIDE, <=100%	T		
		DI-TERT-BUTYL PEROXIDE, <=52%	T		
110-05-4		DI-TERT-BUTYL PEROXIDE, >32-100%	T		
75-91-2		DI-TERT-BUTYL PEROXIDE, >9% WITH TERT-BUTYL HYDROPEROXIDE, <82%	T		
		DI-TERT-BUTYL PEROXYAZELATE	T		
		DITETRADECYL ETHER	D		
12427-38-2		DITHANE M 22	W		
534-52-1		DITROSOL	S		
106-99-0		DIVINYL	D		
821-08-9		DIVINYL ACETYLENE	D		
108-57-6		DIVINYL BENZENE	D		
109-93-3		DIVINYL ETHER, INHIBITED			D
109-93-3		DIVINYL OXIDE			D
77-77-9		DIVINYL SULFONE	D		
110-00-9		DIVINYLENE OXIDE	D		
74-94-2		DMAB	W		
88-85-7		DN 289	S		
3537-86-8		DNBAC	A		
88-85-7		DNBP	S		
70-34-8		DNFB	S		
		DNHM	A		
7585-14-0		DNOAI	A		
534-52-1		DNOC	S		
131-89-5		DNOCHP	S		
88-85-7		DNOSBP	S		
51-28-5	2,4-	DNP (DRY)	S		
88-85-7		DNPB	S		
101-25-7		DNPMT	T		
3710-19-8		DNPRAC	A	W	
101-25-7		DNPT	T		
88-85-7		DNSBP	S		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
121-14-2	2,4,-	DNT	S		
606-20-2	2,6-	DNT	S		
88-85-7		DOW GENERAL (WEED KILLER)	S		
88-85-7		DOW SELECTIVE WEED KILLER	S		
111-76-2		DOWANOL EB ELECTRONICS GRADE	D		
110-80-5		DOWANOL EE	D		
109-86-4		DOWANOL EM	D		
107-98-2		DOWANOL PM GLYCOL ETHER	D		
10049-04-4		DOXCIDE 50	S		
1898-66-4		DPPH	S		
		DTAP	T		
78-11-5		DUOTRATE (DRY)	D		
108-57-6		DVB	D		
609-93-8		DVPC	S		
88-85-7		DYNAMYTE	S		
10031-49-9		DYSPROSIUM NITRATE	O		
88-85-7		DYTOP	S		
563-43-9		EADC	A		
12327-99-0		EASB	A		
12075-68-2		EASC	A		
7758-01-2		EEC NO. E924	O		
534-52-1		EFFUSAN (3436)	S		
628-96-6		EGDN	D		
124-17-4		EKTASOLVE DB ACETATE	D		
110-80-5		EKTASOLVE EE	D		
109-86-4		EKTASOLVE EM	D		
534-52-1		ELGETOL (30)	S		
88-85-7		ELGTOL 318	S		
534-52-1		ELIPOL	S		
110-80-5		EMKANOL	D		
16219-75-3		ENB	D		
4245-77-6		ENNG	S		
12427-38-2		ENT 14875	W		
88-85-7		ENT1,122	S		
88-85-7		EPA PESTICIDE CHEMICAL CODE 037505	S		
20859-73-8		EPA PESTICIDE CHEMICAL CODE 066501	W		
7632-00-0		EPA PESTICIDE CHEMICAL CODE 076204	O		
26628-22-8		EPA PESTICIDE CHEMICAL CODE 107701	S	T	
40487-42-1		EPA PESTICIDE CHEMICAL CODE 108501	S		
512-85-6	1,4-	EPIDIOXY-2-P-MENTHENE	T		
122-60-1	1,2-	EPOXY-3-PHENOXYPROPANE	D		
106-91-2	2,3-	EPOXYPROPYL METHACRYLATE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
993-43-1		EPTD	W		
10031-51-3		ERBIUM NITRATE	O	S	
78-11-5		ERINIT (DRY)	D		
7632-00-0		ERINITRIT	O		
106-99-0		ERYTHRENE	D		
80-43-3		ESPERAL 115RG	T		
1611-62-9		ESPERCARB 840	T		
1611-62-9		ESPERCARB 840 D	T		
1611-62-9		ESPERCARB 840 M	T		
1611-62-9		ESPERCARB 840 M40	T		
1611-62-9		ESPERCARB 840 M70	T		
614-45-9		ESPEROX 10	T		
614-45-9		ESPEROX 101XL	T		
3006-82-4		ESPEROX 28	T		
3006-82-4		ESPEROX 28MD	T		
3006-82-4		ESPEROX 28PD	T		
927-07-1		ESPEROX 31M	T		
26748-41-4		ESPEROX 33M	T		
		ESPEROX 41-25	T		
		ESPEROX 497M	T		
68299-16-1		ESPEROX 545M	T		
29240-17-3		ESPEROX 551M	T		
686-31-7		ESPEROX 570	T		
686-31-7		ESPEROX 570P	T		
		ESPEROX 746M	T		
		ESPEROX 750M	T		
		ESPEROX 939M	T		
		ESPEROX C-496	T		
75-07-0		ETHANAL	D		
533-51-7		ETHANEDIOIC ACID, SILVER SALT	D		
97-90-5	1,2-	ETHANEDIOL DIMETHACRYLATE	D		
79-37-8		ETHANEDIOYL CHLORIDE	W		
110-80-5		ETHANOL, 2-ETHOXY-	D		
		ETHANOLAMINE DINITRATE	D		
75-36-5		ETHANOYL CHLORIDE	W		
108-05-4		ETHENYL ETHANOATE (INHALATION HAZARD)	D		
1067-53-4	6-	ETHENYL-6-(2-METHOXYETHOXY)-2,5,7,10 TETRAOXA-6-SILAUNDECANE	W		
109-93-3		ETHENYLOXYETHENE			D
754-05-2		ETHENYLTRIMETHYLSILANE	W		
60-29-7		ETHER	D		
1634-04-4		ETHER, TERT BUTYL METHYL	D		
140-88-5		ETHOXYCARBONYLETHYLENE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
110-80-5	2-	ETHOXYETHANOL	D		
110-80-5	BETA-	ETHOXYETHANOL	D		
111-90-0	2-(2-	ETHOXYETHOXY)ETHANOL	D		
111-15-9	2-	ETHOXYETHYL ACETATE	D		
110-80-5	2-	ETHOXYETHYL ALCOHOL	D		
140-88-5		ETHYL 2-PROPENOATE	D		
140-88-5		ETHYL ACRYLATE, INHIBITED	D		
75-07-0		ETHYL ALDEHYDE	D		
		ETHYL ALUMINUM CHLORIDE	A		
563-43-9		ETHYL ALUMINUM DICHLORIDE	A		
12075-68-2		ETHYL ALUMINUM SESQUICHLORIDE	A		
628-81-9		ETHYL BUTYL ETHER	D		
110-80-5		ETHYL CELLOSOLVE	D		
1789-58-8		ETHYL DICHLOROSILANE	W		
60-29-7		ETHYL ETHER	D		
629-14-1		ETHYL GLYME	D		
3031-74-1		ETHYL HYDROPEROXIDE	D		
97-63-2		ETHYL METHACRYLATE	D		
540-67-0		ETHYL METHYL ETHER	D		
625-58-1		ETHYL NITRATE	S		
109-95-5		ETHYL NITRITE SOLUTIONS	S	T	
60-29-7		ETHYL OXIDE	D		
22750-93-2		ETHYL PERCHLORATE	D		
140-88-5		ETHYL PROPENOATE	D		
105-37-3		ETHYL PROPIONATE	D		
115-21-9		ETHYL TRICHLOROSILANE	A		
		ETHYL VINYL ETHER	D		
557-20-0		ETHYL ZINC	A	W	
55794-20-2		ETHYL-3,3-DI(T-BUTYLPEROXY)BUTYRATE, 77% OR LESS WITH 23% OR MORE TYPE A DILUENT	T		
67567-23-1		ETHYL-3,3-DI(TERT-AMYLPEROXY) BUTYRATE, <=67%	T		
55794-20-2		ETHYL-3,3-DI-(TERT-BUTYLPEROXY) BUTYRATE, <=52%	T		
		ETHYL-3,3-DI-(TERT-BUTYLPEROXY) BUTYRATE, <=77%	T		
55794-20-2		ETHYL-3,3-DI-(TERT-BUTYLPEROXY) BUTYRATE, >77-100%	T		
4245-77-6	1-	ETHYL-3-NITRO-1-NITROSGUANIDINE	S		
12327-99-0		ETHYLALUMINUM SESQUIBROMIDE	A		
		ETHYLBENZENE HYDROPEROXIDE, <=35%	T		
		ETHYLENE DIAMINE DIPERCHLORATE	D		
97-90-5		ETHYLENE DIMETHACRYLATE	D		
112-48-1		ETHYLENE GLYCOL DIBUTYL ETHER	D		
629-14-1		ETHYLENE GLYCOL DIETHYL ETHER	D		
97-90-5		ETHYLENE GLYCOL DIMETHACRYLATE	D		
110-71-4		ETHYLENE GLYCOL DIMETHYL ETHER	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
628-96-6		ETHYLENE GLYCOL DINITRATE	D		
110-80-5		ETHYLENE GLYCOL ETHYL ETHER	D		
109-86-4		ETHYLENE GLYCOL METHYL ETHER	D		
818-61-1		ETHYLENE GLYCOL MONOACRYLATE	D		
111-76-2		ETHYLENE GLYCOL MONOBUTYL ETHER	D		
0111-76-2		ETHYLENE GLYCOL MONOBUTYL ETHER ACETATE	D		
110-80-5		ETHYLENE GLYCOL MONOETHYL ETHER	D		
111-15-9		ETHYLENE GLYCOL MONOETHYL ETHER ACETATE	D		
109-86-4		ETHYLENE GLYCOL MONOMETHYL ETHER	D		
111-76-2		ETHYLENE GLYCOL N-BUTYL ETHER	D		
79-10-7		ETHYLENECARBOXYLIC ACID	D		
12427-38-2	1,2-	ETHYLENEDIYLBIS(CARBAMODITHIOATO)MANGANESE	W		
151-56-4		ETHYLENIMINE,INHIBITED (POISON INHALATION HAZARD)	D		
151-56-4		ETHYLENIMINE, INHIBITED (POISON INHALATION HAZARD)	D		
123-05-7	2-	ETHYLHEXALDEHYDE	A		
123-05-7	2-	ETHYLHEXANAL	A		
105-57-7		ETHYLIDENE DIETHYL ETHER	D		
16219-75-3	5-	ETHYLIDENE-2-NORBORNENE	D		
811-49-4		ETHYLLITHIUM (IN BENZENE)	A	W	
925-90-6		ETHYLMAGNESIUM BROMIDE (IN SOLVENT)	W		
2386-64-3		ETHYLMAGNESIUM CHLORIDE (IN SOLVENT)	W		
4245-77-6	N-	ETHYL-N-NITRO-N-NITROSOGUANIDINE	S		
993-43-1		ETHYLPHOSPHONOTHIOIC DICHLORIDE	W		
40487-42-1	N-(1-	ETHYLPROPYL)-2,6-DINITRO-3,4-XYLIDINE	S		
40487-42-1	N-(1-	ETHYLPROPYL)-2,6-DINITROXYLIDINE	S		
40487-42-1	N-(1-	ETHYLPROPYL)3,4-DIMETHYL-2,6-DINITROBENZENAMINE	S		
40487-42-1	N-(1-	ETHYLPROPYL)-3,4-DIMETHYL-2,6-DINTROANILINE	S		
74-86-2		ETHYNE (LIQUID)	D		
7440-53-1		EUROPIUM, DISTILLED	W		
		EVE	D		
74-90-8		EVERCYN , ANHYDROUS, STABILIZED (POISON INHALATION HAZARD)	S		
7723-14-0		EXOLIT LPKN-275 (VPK-N 361)	A		
7723-14-0		EXOLITE 405	A		
534-52-1		EXTRAR	S		
10049-04-4		EZ FLOW	S		
10326-21-3		E-Z-OFF	O		
51-28-5		FENOXYL CARBON N	S		
18624-44-7		FERRIC HYDROXIDE	A		
10421-48-4		FERRIC NITRATE	O		
		FERROSILICON (>30% BUT < 90% SILICON)	W		
		FILM (NITROCELLULOSE)	S		
7632-00-0		FILMERINE	O		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
534-52-1		FLAVIN-SANDOZ	S		
7783-41-7		FLUORINE MONOXIDE (POISON INHALATION HAZARD)	A	W	D
70-34-8	1-	FLUORO-2,4-DINITROBENZENE	S		
		FLUOROETHYLENE, INHIBITED	D		
352-13-6		FLUOROPHENYLMAGNESIUM BROMIDE (2.0M IN ETHER)	W		
13537-32-1		FLUOROPHOSPHORIC ACID, ANHYDROUS	W		
7789-21-1		FLUOROSULFONIC ACID	W		
7789-21-1		FLUOROSULFURIC ACID	W		
7789-21-1		FLUOSULFURIC ACID	W		
312-30-1		FNPS	S		
109-87-5		FORMAL	D		
74-90-8		FORMIC ANAMMONIDE, ANHYDROUS, STABILIZED (PIH)	S		
74-90-8		FORMONITRILE, ANHYDROUS, STABILIZED (PIH)	S		
14293-70-0		FREMYS SALT	A	W	
51-28-5	5-	FU	S		
628-86-4		FULMINATE OF MERCURY (DRY)	D		
628-86-4		FULMINATE OF MERCURY (WET >20% WATER)	S		
		FULMINATING GOLD	D		
628-86-4		FULMINATING MERCURY (DRY)	D		
		FULMINATING PLATINUM	D		
5610-59-3		FULMINATING SILVER	D		
506-85-4		FULMINIC ACID	D		
628-86-4		FULMINIC ACID, MERCURY(2+) SALT (DRY)	D		
107-13-1		FUMIGRAIN	D		
20859-73-8		FUMITOXIN	W		
110-00-9		FURAN	D		
110-00-9		FURFURAN	D		
7440-54-2		GADOLINIUM (POWDER)	A		
		GALACTSAN TRINITRATE	D		
13450-90-3		GALLIUM (3) CHLORIDE	W		
13450-90-3		GALLIUM TRICHLORIDE	W		
		GAP	S		
94-36-0		GAROX	T		
94-36-0		GAROX 55A	T		
110-71-4		GDME	D		
7782-65-2		GERMANE (POISON INHALATION HAZARD)	A		
7782-65-2		GERMANIUM HYDRIDE (POISON INHALATION HAZARD)	A		
7783-58-6		GERMANIUM TETRAFLUORIDE	W		
7782-65-2		GERMANIUM TETRAHYDRIDE (POISON INHALATION HAZARD)	A		
101-38-2		GIBBS REAGENT	T		
55-63-0		GILUCOR NITRO	S		
55-63-0		GLONON	S		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
55-63-0		GLYCERINE TRINITRATE	S		
		GLYCEROL MONOGLUCONATE TRINITRATE	D		
		GLYCEROL MONOLACTATE TRINITRATE	D		
55-63-0		GLYCEROL NITRIC ACID TRIESTER	S		
55-63-0		GLYCEROL TRINITRATE	S		
623-87-0		GLYCEROL-1,3-DINITRATE	D		
55-63-0		GLYCERYL NITRATE	S		
55-63-0		GLYCERYL TRINITRATE	S		
2530-83-8	GAMM	GLYCIDOXYPROPYLTRIMETHOXYSILANE	W		
106-90-1		GLYCIDYL ACRYLATE			D
		GLYCIDYL AZIDE POLYMER (GAP) (>60% ETHYL ACETATE)	S		
106-91-2		GLYCIDYL METHACRYLATE	D		
122-60-1		GLYCIDYL PHENYL ETHER	D		
110-71-4		GLYCOL DIMETHYL ETHER	D		
124-17-4		GLYCOL ETHER DB ACETATE	D		
868-77-9		GLYCOL METHACRYLATE	D		
109-86-4		GLYCOL METHYL ETHER	D		
110-80-5		GLYCOL MONOETHYL ETHER	D		
109-86-4		GLYCOL MONOMETHYL ETHER	D		
110-71-4		GLYME	D		
605-69-6		GOLDEN YELLOW	S		
55-63-0		GTN	S		
506-93-4		GUANIDINE NITRATE	S	O	
109-27-3		GUANYL NITROSAMINEOGUANYLTETRAZENE (DRY)	D		
		GUANYL NITROSAMINOQUANYLIDENE HYDRAZINE (WET >30% WATER)	S		
		GUANYL NITROSAMINOQUANYLIDINE HYDRAZINE (DRY)	D		
109-27-3		GUANYL NITROSAMINOQUANYLTETRAZENE (WET >30% WATER)	S		
		GUN POWDER	S		
9004-70-0		GUNCOTTON (DRY)	S		
9004-70-0		GUNCOTTON (WET >25% WATER)	S		
7440-58-6		HAFNIUM METAL, DRY	A		
7440-58-6		HAFNIUM METAL, WET	A		
		HARDENER XB 3787-1 EPOXY CURRING AGENT	W		
78-11-5		HASETHROL (DRY)	D		
534-52-1		HEDOLITE	S		
88-85-7		HEL-FIRE	S		
868-77-9		HEMA	D		
13125-66-1		HEPTYLMAGNESIUM BROMIDE (IN ETHER)	A	W	
40487-42-1		HERBADOX	S		
3457-61-2		HERCULES D-16	T		
		HERCULES DIBHP	T		
100-42-5		HETRON 99P	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
13007-92-6		HEXACARBONYL CHROMIUM	S		
821-08-9	1,5-	HEXADIEN-3-YNE	D		
6569-51-3		HEXAHYDRO-S-TRIAZABORINE	W		
	33669	HEXAMETHYL-1,2,4,5-TETRAOXACYCLONONANE, <=52%	T		
	33669	HEXAMETHYL-1,2,4,5-TETRAOXACYCLONONANE, <=52%	T		
	33669	HEXAMETHYL-1,2,4,5-TETRAOXACYCLONONANE, >52-100%	T		
999-97-3		HEXAMETHYLDISILAZANE	W		
283-66-9		HEXAMETHYLENE TRIPEROXIDE DIAMINE (DRY)	D		
105554-30-1		HEXAMETHYLOL BENZENE HEXANITRATE	D		
	22446	HEXANITRO-3,3'-DIHYDROXYAZOBENZENE(DRY)	D		
		HEXANITROAZOXY BENZENE	D		
	23446	HEXANITRODIPHENYL ETHER	D		
	N,N'	HEXANITRODIPHENYL ETHYLENE DINITRAMINE(DRY)	D		
		HEXANITRODIPHENYL UREA	D		
35860-31-2	22344	HEXANITRODIPHENYLAMINE (2,2,3,4,4,6)	D		
131-73-7		HEXANITRODIPHENYLAMINE (2,2,4,4,6,6)	S		
		HEXANITRODIPHENYLOXIDE	D		
28930-30-5		HEXANITRODIPHENYLSULFIDE (DRY)	S		
918-37-6		HEXANITROETHANE	D		
29135-62-4		HEXANITROOXANILIDE	D		
		HEXANITROSTILBENE	S		
		HEXATONAL, CAST	S		
131-73-7		HEXIL (2,2,4,4,6,6)	S		
131-73-7		HEXITE (2,2,4,4,6,6)	S		
121-82-4		HEXOGEN (WET >15% WATER)	S		
121-82-4		HEXOLITE (DRY)	S		
		HEXOTONOL	S		
112-59-4	N-	HEXYL "CARBITOL"			D
131-73-7		HEXYL (2,2,4,4,6,6)	S		
112-58-3	N-	HEXYL ETHER	D		
		HEXYL MAGNESIUM (IN FLAMMABLE SOLVENT)	A	W	
95718-78-8		HEXYLENE GLYCOL PEROXYNEODECANOATE, <=52%	T		
1338-23-4		HIGH POINT 90	T		
78-63-7		HIMONT HB-331	T		
7722-84-1		HIOXYL (OVER 60% PEROXIDE)	O	S	
999-97-3		HMDS	W		
283-66-9		HMTD (DRY)	D		
2691-41-0		HMX (DRY)	S		
2691-41-0		HMX (WET >15% WATER)	S		
14546-44-2		HYDRAZINE AZIDE	D		
302-01-2		HYDRAZINE BASE, ANHYDROUS	S		
		HYDRAZINE CHLORATE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
67880-17-5		HYDRAZINE DICARBONIC ACID DIAZIDE	D		
		HYDRAZINE PERCHLORATE	D		
73506-32-8		HYDRAZINE SELENATE	D		
302-01-2		HYDRAZINE, ANHYDROUS	S		
19597-69-4		HYDRAZOIC ACID LITHIUM SALT	S		
26628-22-8		HYDRAZOIC ACID, SODIUM SALT	S	T	
74-90-8		HYDROCYANIC ACID (PRUSSIC), UNSTABILIZED	S		
74-90-8		HYDROCYANIC ACID, ANHYDROUS, STABILIZED (PIH)	S		
420-04-2		HYDROGEN CYANAMIDE	T		
74-90-8		HYDROGEN CYANIDE, ANHYDROUS, STABILIZED (PIH)	S		
74-90-8		HYDROGEN CYANIDE, ANHYDROUS, STABILIZED, ABSORBED IN A POROUS INERT MATERIAL. (POISON INHALATION)	S		
7697-37-2		HYDROGEN NITRATE (40% OR LESS)	O		
7697-37-2		HYDROGEN NITRATE (OVER 40%)	O		
7722-84-1		HYDROGEN PEROXIDE SOLUTION, STABILIZED (20 - 40% PEROXIDE)	O		
7722-84-1		HYDROGEN PEROXIDE SOLUTION, STABILIZED (8 - 20% PEROXIDE)	O		
7722-84-1		HYDROGEN PEROXIDE SOLUTION, STABILIZED, (40 - 60% PEROXIDE)	O		
7722-84-1		HYDROGEN PEROXIDE SOLUTION, STABILIZED, (OVER 60% PEROXIDE)	O	S	
463-56-9		HYDROGEN THIOCYANATE (POLYMERIZATION HAZARD)	D		
7722-84-1		HYDROPEROXIDE (OVER 60% PEROXIDE)	O	S	
95718-78-8	3-	HYDROXY-1,1-DIMETHYLBUTYL PEROXY NEODECANOATE, <=52%	T		
51-28-5	1-	HYDROXY-2,4-DINITROBENZENE	S		
109-86-4	1-	HYDROXY-2-METHOXYETHANE	D		
123333-53-9	1-	HYDROXYBENZOTRIAZOLE HYDRATE	T		
	3-2-	HYDROXYETHOXY-4-PYRROLIDIN-1-YL-BENZENE DIAZONIUM ZINC CHLORIDE	T		
818-61-1	2-	HYDROXYETHYL ACRYLATE	D		
868-77-9	2-	HYDROXYETHYL METHACRYLATE	D		
7803-49-8		HYDROXYLAMINE	A		
59917-23-6		HYDROXYLAMINE IODIDE	D		
7803-49-8		HYDROXYLAMMONIUM	A		
924-42-5	N-(HYDROXYMETHYL)-2-PROPENAMIDE	D		
924-42-5	N-(HYDROXYMETHYL)ACRYLAMIDE	D		
923-26-2		HYDROXYPROPYL METHACRYLATE	D		
101-68-8		HYLENE M-50	W		
14448-38-5		HYPONITROUS ACID	D		
109-95-5		HYPONITROUS ETHER	S	T	
12090-38-9		IBASC	A	W	
30674-80-7	BETA-	IEM **INHIBITOR**	D		
75-78-5		INERTON AW-DMCS	A	W	
7332-16-3		INOSITOL HEXANITRATE(DRY)	D		
		INULIN TRINITRATE(DRY)	D		
		IODIDE OF MILLON'S BASE	D		
14696-82-3		IODINE AZIDE (DRY)	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
7783-66-6		IODINE FLUORIDE	W		
7783-66-6		IODINE PENTAFLUORIDE	W		
16029-98-4		IODOTRIMETHYL SILANE	W		
		IODOXY COMPOUNDS (DRY)	D		
108-20-3		IPE	D		
110-46-3		IPN	A		
105-64-6		IPP	T		
		IRIDIUM NITRATOPENTAMINE IRIIDIUM NITRATE	D		
18624-44-7		IRON (III) HYDROXIDE	A		
13463-40-6		IRON CARBONYL (POISON INHALATION HAZARD)	A		
10421-48-4		IRON NITRATE	O		
13463-40-6		IRON PENTACARBONYL (POISON INHALATION HAZARD)	A		
544-01-4		ISOAMYL ETHER	D		
110-46-3		ISOAMYL NITRITE	A		
544-01-4		ISOAMYL OXIDE	D		
106-63-8		ISOBUTYL ACRYLATE	D		
97-86-9		ISOBUTYL METHACRYLATE	D		
		ISOBUTYL VINYL ETHER	D		
1888-87-5		ISOBUTYLALUMINUM DICHLORIDE	A	W	
12090-38-9		ISOBUTYLALUMINUM SESQUICHLORIDE	A	W	
538-93-2		ISOBUTYLBENZENE	S		
926-62-5		ISOBUTYLMAGNESIUM BROMIDE (IN SOLVENT)	W		
5674-02-2		ISOBUTYLMAGNESIUM CHLORIDE (IN SOLVENT)	W		
624-83-9		ISOCYANATO METHANE (POISON INHALATION HAZARD)	W		
30674-80-7	BETA-	ISOCYANATOETHYL METHACRYLATE	D		
624-83-9		ISOCYANIC ACID, METHYL ESTER (POISON INHALATION HAZARD)	W		
101-68-8		ISOCYANIC ACID, METHYLENEDI-P-PHENYLENE ESTER	W		
1330-61-6		ISODECYL ACRYLATE	D		
101-68-8		ISONATE 125M (125MF)	W		
		ISONONANOYL PEROXIDE, <=38%	T		
		ISONONANOYL PEROXIDE, <=52% AS A STABLE DISPERSION IN WATER	T		
3851-87-4		ISONONANOYL PEROXIDE, >38-82%	T		
110-46-3		ISOPENTYL ALCOHOL NITRITE	A		
544-01-4		ISOPENTYL ETHER	D		
110-46-3		ISOPENTYL NITRITE	A		
78-79-5		ISOPRENE, INHIBITED	D		
31259-92-4		ISOPRENYL	A	W	
31259-92-4		ISOPRENYLALUMINUM	A	W	
126-98-7		ISOPROPENE CYANIDE	D		
116-11-0		ISOPROPENYL METHYL ETHER	D		
98-83-9		ISOPROPENYLBENZENE	D		
126-98-7		ISOPROPENYLNITRILE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
108-20-3	2-	ISOPROPOXYPROPANE	D		
108-20-3		ISOPROPYL ETHER	D		
		ISOPROPYL LITHIUM (IN FLAMMABLE SOLVENT)	A		
105-64-6		ISOPROPYL PERCARBONATE, <=52%	T		
105-64-6		ISOPROPYL PERCARBONATE, >52-100%	T		
		ISOPROPYL SEC-BUTYL PEROXYDICARBONATE =<32% + DI-SEC-BUTYL PEROXYDICARBONATE =<15-18% + DI-	T		
		ISOPROPYL SEC-BUTYL PEROXYDICARBONATE =<52% + DI-SEC-BUTYL PEROXYDICARBONATE =<28% + DI-ISOPROPYL	T		
13373-32-5	2-	ISOPROPYL-4-(OR 5-) NITROIMIDAZOLE	S		
98-82-8		ISOPROPYLBENZENE	D		
98-82-8		ISOPROPYLBENZOL	D		
		ISOPROPYLCUMYL HYDROPEROXIDE, <=72%	T		
920-39-8		ISOPROPYLMAGNESIUM BROMIDE (IN SOLVENT)	W		
1068-55-9		ISOPROPYLMAGNESIUM CHLORIDE (IN SOLVENT)	W		
463-56-9		ISOTHIOCYANIC ACID (POLYMERIZATION HAZARD)	D		
		IVE	D		
88-85-7		IVOSIT	S		
94-36-0		JB-4 CATALYST	T		
26628-22-8		KAZOE	S	T	
88-85-7		KILOSEB	S		
55-63-0		KLAVIKORDAL	S		
88-85-7		KNOX-WEED	S		
534-52-1		KREOZAN	S		
534-52-1		KREZOTOL 50	S		
12427-38-2		KYPMAN 80	W		
88-85-7		LADOB	S		
7439-91-0		LANTHANUM	W		
10277-43-7		LANTHANUM NITRATE	O		
88-85-7		LASEB	S		
105-74-8		LAUROX	T		
105-74-8		LAUROYL PEROXIDE, <=100%	T		
105-74-8		LAUROYL PEROXIDE, <=42% AS A STABLE DISPERSION IN WATER	T		
4111-54-0		LDA	A	W	
4111-54-0		LDA 9505	A	W	
13424-46-9		LEAD AZIDE (DRY)	D		
13424-46-9		LEAD AZIDE (WET WITH >20% WATER)	S		
10099-74-8		LEAD DINITRATE	O		
51317-24-9		LEAD MONONITRORESORCINATE (DRY)	D		
51317-24-9		LEAD MONONITRORESORCINATE (WET)	S		
10099-74-8		LEAD NITRATE	O		
51317-24-9		LEAD NITRORESORCINATE (DRY)	D		
51317-24-9		LEAD NITRORESORCINATE (WET)	S		
13637-76-8		LEAD PERCHLORATE	O		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
6477-64-1		LEAD PICRATE (DRY)	D		
63918-97-8		LEAD STYPHNATE	D		
63918-97-8		LEAD STYPHNATE (DRY)	D		
63918-97-8		LEAD STYPHNATE (WET >20% WATER)	S		
63918-97-8		LEAD TRINITRORESORCINATE (DRY)	D		
63918-97-8		LEAD TRINITRORESORCINATE (WET >20% WATER)	S		
		LEKUTHERM HARDENER F	W		
55-63-0		LENITRAL	S		
302-01-2		LEVOZINE	S		
4039-32-1		LHS (1.0 M IN HEXANES)	W	A	
4039-32-1		LHS (1.0 M IN THF)	W	A	
10124-37-5		LIME NITRATE	O		
156-62-7		LIME NITROGEN, NOT HYDRATED >0.1% CALCIUM CARBIDE	W		
534-52-1		LIPAN	S		
88-85-7		LIRO DNBP	S		
7439-93-2		LITHIUM	W		
6867-30-7		LITHIUM ACETYLIDE ETHYLENEDIAMINE COMPLEX	W		
14128-54-2		LITHIUM ALUMINUM DEUTERIDE	W		
16853-85-3		LITHIUM ALUMINUM HYDRIDE	W		
16853-85-3		LITHIUM ALUMINUM HYDRIDE (IN SOLVENT)	W		
7782-89-0		LITHIUM AMIDE, POWDERED	W		
19597-69-4		LITHIUM AZIDE	S		
		LITHIUM BATTERY	W		
4039-32-1		LITHIUM BIS (TRIMETHYLSILYL) AMIDE (1.0 M SOLN. IN HEXANES)	W	A	
4039-32-1		LITHIUM BIS (TRIMETHYLSILYL) AMIDE (1.0 M SOLUTION IN THF)	W	A	
16949-15-8		LITHIUM BOROHYDRIDE	W		
16733-97-4		LITHIUM CYCLOPENTADIENYLIDE	W		
816-43-3		LITHIUM DIETHYLAMIDE	A	W	
4111-54-0		LITHIUM DIISOPROPYLAMIDE	A	W	
811-49-4		LITHIUM ETHYL (IN BENZENE)	A	W	
64082-35-5		LITHIUM FERROSILICON	W		
4039-32-1		LITHIUM HEXAMETHYLDISILAZIDE (1.0 M IN HEXANES)	W	A	
4039-32-1		LITHIUM HEXAMETHYLDISILAZIDE (1.0 M IN THF)	W	A	
7580-67-8		LITHIUM HYDRIDE	W		
7580-67-8		LITHIUM HYDRIDE IN FUSED SOLID FORM	W		
865-34-9		LITHIUM METHOXIDE	W		
7790-69-4		LITHIUM NITRATE	O		
26134-62-3		LITHIUM NITRIDE	W		
68848-64-6		LITHIUM SILICON	W		
1907-33-1		LITHIUM T-BUTOXIDE	A	W	
16853-85-3		LITHIUM TETRAHYDRIDOALUMINATE	W		
17476-04-9		LITHIUM TRI-BUTOXY ALUMINUM HYDRIDE (IN SOLVENT)	W		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

<i>Chemical CAS#</i>	<i>Prefix</i>	<i>Chemical Name</i>	<i>Reactive Chemical Stimulus 1</i>	<i>Reactive Chemical Stimulus 2</i>	<i>Reactive Chemical Stimulus 3</i>
22560-16-3		LITHIUM TRIETHYL BOROHYDRIDE (IN THF)	W		
38721-52-7		LITHIUM TRI-SEC-BUTYLBOROHYDRIDE (IN THF)	A	W	
12427-38-2		LONOCOL M	W		
		LUCEMUL 188E-65M	T		
1611-62-9		LUCEMUL 223E-65M	T		
94-36-0		LUCIDOL-70	T		
94-36-0		LUCIDOL-78	T		
94-36-0		LUCIDOL-98	T		
26748-41-4		LUP 10	T		
927-07-1		LUP 11	T		
78-63-7		LUPERCO 101-XL	T		
1068-27-5		LUPERCO 130-XL	T		
		LUPERCO 230-SRL	T		
		LUPERCO 230-XL	T		
6731-36-8		LUPERCO 231-KE	T		
6731-36-8		LUPERCO 231-P75	T		
6731-36-8		LUPERCO 231-SRL	T		
6731-36-8		LUPERCO 231-XL	T		
55794-20-2		LUPERCO 233-XL	T		
3006-86-8		LUPERCO 331-XL	T		
94-36-0		LUPERCO ACT	T		
94-36-0		LUPERCO AFR-400	T		
94-36-0		LUPERCO AFR-520	T		
94-36-0		LUPERCO ANS	T		
94-36-0		LUPERCO AST	T		
133-14-2		LUPERCO CDB	T		
133-14-2		LUPERCO CST	T		
		LUPERCO PMA-25	T		
		LUPERCO PMA-40	T		
26748-41-4		LUPEROX 10	T		
78-63-7		LUPEROX 101XL-45	T		
26748-41-4		LUPEROX 10-M75	T		
2618-77-1		LUPEROX 118	T		
927-07-1		LUPEROX 11-M75	T		
1068-27-5		LUPEROX 130XL-45	T		
		LUPEROX 188-M75	T		
3025-88-5		LUPEROX 2,5-2,5	T		
41935-39-1		LUPEROX 204	T		
		LUPEROX 229	T		
		LUPEROX 229-W40	T		
995-33-5		LUPEROX 230	T		
		LUPEROX 256	T		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

<i>Chemical CAS#</i>	<i>Prefix</i>	<i>Chemical Name</i>	<i>Reactive Chemical Stimulus 1</i>	<i>Reactive Chemical Stimulus 2</i>	<i>Reactive Chemical Stimulus 3</i>
3006-82-4		LUPEROX 26	T		
3006-82-4		LUPEROX 26-M50	T		
3006-82-4		LUPEROX 26-P50	T		
80-43-3		LUPEROX 500R	T		
80-43-3		LUPEROX 500T	T		
68299-16-1		LUPEROX 546-M75	T		
29240-17-3		LUPEROX 554-M75	T		
68860-54-8		LUPEROX 570	T		
686-31-7		LUPEROX 575	T		
686-31-7		LUPEROX 575-M75	T		
686-31-7		LUPEROX 575-P75	T		
		LUPEROX 688-M50	T		
107-71-1		LUPEROX 7M50	T		
107-71-1		LUPEROX 7M75	T		
25155-25-3		LUPEROX 802	T		
109-13-7		LUPEROX 80-M75	T		
94-36-0		LUPEROX A70S	T		
94-36-0		LUPEROX A98	T		
94-36-0		LUPEROX AFR400	T		
94-36-0		LUPEROX ANS55	T		
94-36-0		LUPEROX ANS55P	T		
94-36-0		LUPEROX ATC50	T		
762-12-9		LUPEROX DEC	T		
2155-71-7		LUPEROX KDB	T		
105-74-8		LUPEROX LP	T		
1931-62-2		LUPEROX PMA	T		
123-23-9		LUPEROX SAP	T		
75-91-2		LUPEROX TBH70X	T		
75-91-2		LUPEROX TBH90	T		
2372-21-6		LUPEROX TBICM75	T		
26748-41-4		LUPERSOL 10	T		
78-63-7		LUPERSOL 101	T		
78-63-7		LUPERSOL 101-XL	T		
26748-41-4		LUPERSOL 10-M50	T		
26748-41-4		LUPERSOL 10-M75	T		
927-07-1		LUPERSOL 11	T		
		LUPERSOL 11-20H	T		
927-07-1		LUPERSOL 11-M45	T		
1068-27-5		LUPERSOL 130	T		
1068-27-5		LUPERSOL 130XL	T		
		LUPERSOL 188-M75	T		
3851-87-4		LUPERSOL 219-M60	T		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure

O - Strong Oxidizing Materials

S - Shock, Friction, Static Charge

W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)

P - Pressure Release (for future use)

T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

<i>Chemical CAS#</i>	<i>Prefix</i>	<i>Chemical Name</i>	<i>Reactive Chemical Stimulus 1</i>	<i>Reactive Chemical Stimulus 2</i>	<i>Reactive Chemical Stimulus 3</i>
2167-23-9		LUPERSOL 220-D50	T		
16066-38-9		LUPERSOL 221	T		
1611-62-9		LUPERSOL 223	T		
1611-62-9		LUPERSOL 223-M40	T		
1611-62-9		LUPERSOL 223-M70	T		
1611-62-9		LUPERSOL 223-M75S	T		
1611-62-9		LUPERSOL 223-S	T		
1611-62-9		LUPERSOL 223-T70	T		
37187-22-7		LUPERSOL 224	T		
19910-65-7		LUPERSOL 225	T		
19910-65-7		LUPERSOL 225-M	T		
19910-65-7		LUPERSOL 225-M30	T		
19910-65-7		LUPERSOL 225-M50	T		
19910-65-7		LUPERSOL 225-M60S	T		
19910-65-7		LUPERSOL 225-S	T		
19910-65-7		LUPERSOL 225-X30	T		
19910-65-7		LUPERSOL 226	T		
3179-56-4		LUPERSOL 228Z	T		
995-33-5		LUPERSOL 230	T		
6731-36-8		LUPERSOL 231	T		
6731-36-8		LUPERSOL 231-P75	T		
		LUPERSOL 233-M75	T		
55794-20-2		LUPERSOL 233-XL	T		
		LUPERSOL 256	T		
		LUPERSOL 288-M75	T		
3006-86-8		LUPERSOL 331-80B	T		
3006-86-8		LUPERSOL 331-80M	T		
23383-59-7		LUPERSOL 47-M75	T		
		LUPERSOL 531-80B	T		
		LUPERSOL 531-80M	T		
67567-23-1		LUPERSOL 533-M75	T		
68299-16-1		LUPERSOL 546-M75	T		
29240-17-3		LUPERSOL 554-M50	T		
29240-17-3		LUPERSOL 554-M75	T		
		LUPERSOL 555-M60	T		
686-31-7		LUPERSOL 575	T		
686-31-7		LUPERSOL 575-M75	T		
686-31-7		LUPERSOL 575-P75	T		
686-31-7		LUPERSOL 575-T40	T		
95718-78-8		LUPERSOL 610M50	T		
		LUPERSOL 688-M50	T		
107-71-1		LUPERSOL 70	T		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
		LUPERSOL 701-M75	T		
107-71-1		LUPERSOL 75M	T		
107-71-1		LUPERSOL 76M	T		
109-13-7		LUPERSOL 80	T		
3457-61-2		LUPERSOL 801	T		
1338-23-4		LUPERSOL DDM-30	T		
1338-23-4		LUPERSOL DDM-9	T		
1338-23-4		LUPERSOL DELTA-X-9	T		
1338-23-4		LUPERSOL DFR	T		
1338-23-4		LUPERSOL DHD-9	T		
		LUPERSOL DP-275B-25	T		
1338-23-4		LUPERSOL DSW-9	T		
2155-71-7		LUPERSOL KDB	T		
3006-82-4		LUPERSOL P-31	T		
3006-82-4		LUPERSOL PDO	T		
3006-82-4		LUPERSOL PMS	T		
		LUPERSOL TAEC	T		
2372-21-6		LUPERSOL TBIC-M75	T		
		LUPRESOL 11-MC20	T		
107-02-08		MAGNACIDE H (POISON INHALATION HAZARD)	D		
7439-95-4		MAGNESIUM ALLOYS, POWDER	W		
		MAGNESIUM ALUMINUM PHOSPHIDE	W		
7789-36-8		MAGNESIUM BROMATE	O		
10326-21-3		MAGNESIUM CHLORATE	O		
		MAGNESIUM DIAMIDE	A		
557-18-6		MAGNESIUM DIETHYL	A	W	
555-54-4		MAGNESIUM DIPHENYL	A		
69011-63-8		MAGNESIUM DROSS (WET OR HOT)	D		
2414-98-4		MAGNESIUM ETHOXIDE	W		
7439-95-4		MAGNESIUM GRANULES COATED, PARTICLE SIZE >149 MICRONS	W		
7693-27-8		MAGNESIUM HYDRIDE	W		
7439-95-4		MAGNESIUM METAL (PELLETS, TURNINGS, OR RIBBON)	A	W	
10377-60-3		MAGNESIUM NITRATE	O		
10034-81-8		MAGNESIUM PERCHLORATE	O		
12057-74-8		MAGNESIUM PHOSPHIDE	W		
22831-39-6		MAGNESIUM SILICIDE	W		
7439-95-4		MAGNESIUM, POWDER	W		
74-39-5		MAGNESON	S		
10326-21-3		MAGRON	O		
12427-38-2		MANEB, STABILIZED	W		
12427-38-2		MANESAN	W		
12427-38-2		MANEX	W		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
15825-70-4		MANEXIN	S		
10170-69-1		MANGANESE CARBONYL	A		
12427-38-2		MANGANESE ETHYLENE-1,2-BISDITHIOCARBAMATE, STABILIZED	W		
10377-66-9		MANGANESE NITRATE	O		
12427-38-2		MANGANOUS ETHYLENEBIS(DITHIOCARBAMATE)	W		
10377-66-9		MANGANOUS NITRATE	O		
		MANNITAN TETRANITRATE	D		
15825-70-4		MANNITOL HEXANITRATE (DRY)	D		
15825-70-4		MANNITOL HEXANITRATE (WET >40% WATER)	S		
15825-70-4		MANNITOL NITRATE	S		
15825-70-4		MANNITRIN	S		
12427-38-2		MANZATE (D)	W		
78-11-5		MARTRATE-45 (DRY)	D		
12542-85-7		MASC	A	W	
15825-70-4		MAXITATE	S		
10326-21-3		MC DEFOLIANT	O		
101-68-8		MDI	W		
15825-70-4		MEDEMANOL	S		
1338-23-4		MEK PEROXIDE, <=40%	T		
1338-23-4		MEK PEROXIDE, <=45%	T		
1338-23-4		MEK PEROXIDE, <=52%	T		
		MEK PEROXIDE, >52%	T	S	
88-89-1		MELINITE (DRY)	S		
88-89-1		MELINITE (WET > 30% WATER)	S		
	P-	MENTHYL HYDROPEROXIDE, <=72%	T		
26762-92-5	P-	MENTHYL HYDROPEROXIDE, >72-100%	T		
	5-	MERCAPTOTETRAZOL-1-ACETIC ACID	S		
628-86-4		MERCURIC CYANATE (DRY)	D		
1335-31-5		MERCURIC OXYCYANIDE, DESENSITIZED	S	T	
1335-31-5		MERCURIC OXYCYANIDE, NOT DESENSITIZED	S	T	
38232-63-2		MERCUROUS AZIDE	D		
7616-83-3		MERCURY (2) PERCHLORATE	O	S	
37297-87-3		MERCURY ACETYLIDE	D		
1335-31-5		MERCURY CYANIDE OXIDE, DESENSITIZED	S	T	
628-86-4		MERCURY FULMINATE (DRY)	D		
628-86-4		MERCURY FULMINATE (WET >20% WATER)	S		
		MERCURY IODIDE AQUABASIC AMMONBASIC	D		
12136-15-1		MERCURY NITRIDE	D		
1335-31-5		MERCURY OXYCYANIDE, DESENSITIZED	S	T	
1335-31-5		MERCURY OXYCYANIDE, NOT DESENSITIZED	S	T	
110-88-3		METAFORMALDEHYDE	D		
		METAL SALTS OF METHYL NITRAMINE (DRY)	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
78-85-3		METHACROLEIN	D		
78-85-3		METHACRYLALDEHYDE	D		
79-41-4	ALPHA	METHACRYLIC ACID	D		
80-62-6		METHACRYLIC ACID,	D		
80-62-6		METHACRYLIC ACID, METHYL ESTER	D		
126-98-7		METHACRYLONITRILE	D		
2530-85-0	GAMM	METHACRYLOXYPROPYLTRIMETHOXY SILANE	W		
924-42-5	N	METHANOLACRYLAMIDE	D		
		METHAZOIC ACID	D		
4435-53-4	3-	METHOXY BUTYL ACETATE	D		
4435-53-4	3-	METHOXY-1-BUTANOL ACETATE	D		
109-86-4	2-	METHOXY-1-ETHANOL	D		
107-98-2	1-	METHOXY-2-PROPANOL	D		
4435-53-4	3-	METHOXYBUTYL ACETIC ACID	D		
96-33-3		METHOXYCARBONYLETHYLENE	D		
107-30-2		METHOXYCHLOROMETHANE (POSION INHALATION HAZARD)	D	W	
540-67-0		METHOXYETHANE	D		
109-86-4	2-	METHOXYETHANOL	D		
109-86-4		METHOXYETHANOL	D		
111-77-3	2-(2-	METHOXYETHOXY)ETHANOL	D		
109-86-4	2-	METHOXYETHYL ALCOHOL	D		
111-96-6	2-	METHOXYETHYL ETHER	D		
107-25-5		METHOXYETHYLENE	D		
109-86-4		METHOXYETHYLENE GLYCOL	D		
25414-22-6	2-	METHOXYFURAN	D		
109-86-4		METHOXYHYDROXYETHANE	D		
107-30-2		METHOXYMETHYL CHLORIDE (POISON INHALATION HAZARD)	D	W	
557-17-5	1-	METHOXYPROPANE	D		
116-11-0	2-	METHOXYPROPENE	D		
		METHOXSILANE	W		
111-77-3	2BETA	METHYL "CARBITOL"	D		
109-86-4		METHYL "CELLOSOLVE"	D		
1634-04-4		METHYL 1,1-DIMETHYLETHYL ETHER	D		
80-62-6		METHYL 2-METHYL-2-PROPENOATE	D		
80-62-6		METHYL 2-METHYLPROPENOATE	D		
74-99-7		METHYL ACETYLENE	D		
96-33-3		METHYL ACRYLATE	D		
126-98-7		METHYL ACRYLONITRILE	D		
80-62-6		METHYL A-METHYLACRYLATE	D		
121-43-7		METHYL BORATE	W		
80-62-6		METHYL ESTER	D		
115-10-6		METHYL ETHER	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
1338-23-4		METHYL ETHYL KETONE PEROXIDE(S), <=40%	T		
1338-23-4		METHYL ETHYL KETONE PEROXIDE(S), <=45%	T		
1338-23-4		METHYL ETHYL KETONE PEROXIDE(S), <=52%	T		
		METHYL ETHYL KETONE PEROXIDE, >52%	T	S	
109-86-4		METHYL GLYCOL	D		
37206-20-5		METHYL ISOBUTYL KETONE PEROXIDE, <=62%	T		
		METHYL ISOBUTYL KETONE PEROXIDE, >62%	T	S	
624-83-9		METHYL ISOCYANATE (POISON INHALATION HAZARD)	W		
814-78-8		METHYL ISOPROPENYL KETONE, INHIBITED	D		
917-54-4		METHYL LITHIUM	A		
917-54-4		METHYL LITHIUM (1.0M IN THF)	A	W	
80-62-6		METHYL METHACRYLATE MONOMER,INHIBITED	D		
		METHYL NITRAMINE	D		
598-58-3		METHYL NITRATE	D		
		METHYL NITRITE	D		
115-10-6		METHYL OXIDE	D		
109-86-4		METHYL OXITOL	D		
		METHYL PHOSPHONOUS DICHLORIDE,PYROPHORIC LIQUID (PIH)	D		
		METHYL PHOSPHOROUS DICHLORIDE (POISON INHALATION HAZARD)	A		
606-35-9		METHYL PICRATE	S		
		METHYL PICRIC ACID (HEAVY METAL SALTS OF)	D		
96-33-3		METHYL PROP-2-ENOATE	D		
96-33-3		METHYL PROPENOATE	D		
557-17-5		METHYL PROPYL ETHER	D		
98-83-9	ALPHA	METHYL STYRENE	D		
1634-04-4		METHYL TERT-BUTYL ETHER	D		
96-47-9		METHYL TETRAHYDROFURAN	D		
		METHYL TRIMETHYLOL METHANE TRINITRATE	D		
107-25-5		METHYL VINYL ETHER	D		
78-94-4		METHYL VINYL KETONE,(POISON INHALATION HAZARD)	D		
78-79-5	2-	METHYL-1,3-BUTADIENE	D		
4435-53-4		METHYL-1,3-BUTYLENE GLYCOL ACETATE	D		
606-20-2	2-	METHYL-1,3-DINITROBENZENE	S		
684-93-5	1-	METHYL-1-NITROSOUREA	T		
97-63-2	2-	METHYL-2 PROPENOIC ACID, ETHYL ESTER	D		
121-14-2	1-	METHYL-2,4-DINITROBENZENE	S		
534-52-1	6-	METHYL-2,4-DINITROPHENOL	S		
606-20-2	1-	METHYL-2,6-DINITROBENZENE	S		
1634-04-4	2-	METHYL-2-METHOXY PROPANE	D		
1634-04-4	2-	METHYL-2-METHOXYPROPANE	D		
594-70-7	2-	METHYL-2-NITROPROPANE	S		
126-98-7	2-	METHYL-2-PROPENENITRILE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
70-25-7	1-	METHYL-3-NITRO-1-NITROSOGUANIDINE	S	T	
534-52-1	2-	METHYL-4,6-DINITROPHENOL	S		
126-98-7	2-	METHYLACRYLONITRILE	D		
109-87-5		METHYLAL	D		
12542-85-7		METHYLALUMINUM SESQUICHLORIDE	A	W	
		METHYLAMINE DINITRAMINE AND DRY SALTS THEREOF	D		
		METHYLAMINE NITROFORM	D		
		METHYLAMINE PERCHLORATE (DRY)	D		
75-55-8	2-	METHYLAZIRIDINE, INHIBITED	D		
101-68-8		METHYLBISPHENYL ISOCYANATE	W		
110-46-3	3-	METHYLBUTANOL NITRITE	A		
110-46-3	3-	METHYLBUTYL NITRITE	A		
107-30-2		METHYLCHLOROMETHYL ETHER (POISON INHALATION HAZARD)	D	W	
		METHYLCYCLOHEXANONE PEROXIDE(S), <=67%	T		
75-54-7		METHYLDICHLOROSILANE	W		
101-68-8		METHYLENE BISPHENYL ISOCYANATE	W		
101-68-8		METHYLENE DI(PHENYLENE ISOCYANATE)	W		
		METHYLENE GLYCOL DINITRATE	D		
101-68-8		METHYLENEBIS (PHENYLISOCYANATE)	W		
101-68-8		METHYLENEBIS(4-ISOCYANATOBENZENE)	W		
101-68-8	1,1-	METHYLENEBIS(4-ISOCYANATOBENZENE)	W		
101-68-8		METHYLENEBIS(4-PHENYLENE ISOCYANATE)	W		
101-68-8	4,4-	METHYLENEDIPHENYL ISOCYANATE	W		
13373-32-5	2-(1-	METHYLETHYL)-5-NITRO-1H-IMIDAZOLE	S		
98-82-8	(1-	METHYLETHYL)BENZENE	D		
75-55-8	2-	METHYLETHYLENIMINE	D		
534-22-5	2-	METHYLFURAN			D
	ALPHA	METHYLGLUCOSIDE TETRANITRATE	D		
	ALPHA	METHYLGLYCEROL TRINITRATE	D		
75-16-1		METHYLMAGNESIUM BROMIDE IN ETHYL ETHER	W		
676-58-4		METHYLMAGNESIUM CHLORIDE (IN THF)	W		
917-64-6		METHYLMAGNESIUM IODIDE (IN DIETHYL ETHER)	W		
70-25-7		METHYLNITRONITROSOGUANIDINE	S	T	
684-93-5	N-	METHYLNITROSO UREA	T		
684-93-5		METHYLNITROSOUREA	T		
70-25-7	N-	METHYL-N-NITRO-N-NITROSOGUANIDINE	S	T	
684-93-5	N-	METHYL-N-NITROSOUREA	T		
924-42-5	N-	METHYLOLACRYLAMIDE	D		
79-41-4	2-	METHYLPROPENOIC ACID	D		
88-85-7	2-(1-	METHYLPROPYL-4,6-DINITROPHENOL	S		
75-79-6		METHYLSILICOCHLOROFORM	W	A	
75-79-6		METHYLSILYL TRICHLORIDE	W	A	

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
75-79-6		METHYLTRICHLOROSILANE	W	A	
1185-55-3		METHYLTRIMETHOXYSILANE	W		
78-11-5		METRANIL (DRY)	D		
624-83-9		MIC (POISON INHALATION HAZARD)	W		
101-25-7		MICROPOR	T		
101-25-7		MIKROFOR N	T		
80-62-6		MMA	D		
70-25-7		MNNG	S	T	
684-93-5		MNU	T		
15825-70-4		MOLOID	S		
1888-87-5		MONIBAC	A	W	
107-30-2		MONOCHLORODIMETHYL ETHER (POISON INHALATION HAZARD)	D	W	
75-01-4		MONOCHLOROETHYLENE	D		
542-88-1		MONOCHLOROMETHYL ETHER	D		
107-30-2		MONOCHLOROMETHYL METHYL ETHER (PIH)	D	W	
75-77-4		MONOCHLOROTRIMETHYLSILICON	W		
13537-32-1		MONOFLUOROPHOSPHORIC ACID, ANHYDROUS	W		
109-86-4		MONOMETHYL GLYCOL	D		
924-42-5		MONOMETHYLOLACRYLAMIDE	D		
75-79-6		MONOMETHYLTRICHLOROSILANE	W	A	
7803-62-5		MONOSILANE	A	W	
4856-95-5		MORPHOLINE BOROXYDRIDE	W		
4856-95-5		MORPHOLINEBORANE	W		
1634-04-4		MTBE	D		
81-15-2		MUSK XYLENE	S		
107-25-5		MVE	D		
78-11-5		MYCARDOL (DRY)	D		
55-63-0		MYOGLYCERIN	S		
101-68-8		NACCONATE 300	W		
		NAPHITE	S		
		NAPHTHALENE DIOZONIDE	D		
605-69-6		NAPHTHOL YELLOW	S		
		NAPHTHYL AMINEPERCHLORATE	D		
7632-00-0		NCI-C02084	O		
26628-22-8		NCI-C06462	S	T	
101-68-8		NCI-C50668	W		
924-42-5		NCI-C60333	D		
123-91-1		NE 220	D		
108-60-1		NEMAMORT	D		
557-17-5		NEOTHYL	D		
12427-38-2		NEREB	W		
12427-38-2		NESPOR	W		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
534-52-1		NEUDORFF DN 50	S		
16774-21-3		NEUTRAZIDE	O		
13463-39-3		NICKEL CARBONYL (POISON INHALATION HAZARD)	A		
17861-62-0		NICKEL DINITRITE	O		
13478-00-7		NICKEL NITRATE	O		
17861-62-0		NICKEL NITRITE	O		
		NICKEL PICRATE	D		
13463-39-3		NICKEL TETRACARBONYL (POISON INHALATION HAZARD)	A		
13478-00-7		NICKELOUS NITRATE	O		
55-63-0		NIGLIN	S		
55-63-0		NIGLYCON	S		
78-11-5		NIPERYT (DRY)	D		
78-11-5		NIPERYTH (DRY)	D		
7697-37-2		NITAL (40% OR LESS)	O		
7697-37-2		NITAL (OVER 40%)	O		
7757-79-1		NITER	O		
55-63-0		NITORA	S		
15825-70-4		NITRANITOL	S		
		NITRATED PAPER (UNSTABLE)	D		
		NITRATES OF DIAZONIUM COMPOUNDS	D		
7697-37-2		NITRIC ACID (>70%)	O		
7697-37-2		NITRIC ACID (70% OR LESS)	O		
598-58-3		NITRIC ACID METHYL ESTER (LESS THAN 10% WITH ETHANOL)	D		
13473-90-0		NITRIC ACID, ALUMINUM SALT	O		
7789-18-6		NITRIC ACID, CESIUM SALT	O		
		NITRIC ACID, RED FUMING (POISON INHALATION HAZARD)	O		
10102-45-1		NITRIC ACID, THALLIUM(1+) SALT	O		
55-63-0		NITRIN	S		
55-63-0		NITRINE	S		
298-83-9		NITRO BLUE TETRAZOLIUM	S		
298-83-9		NITRO BT	S		
	1-	NITRO HYDANTOIN	D		
		NITRO ISOBUTANE TRIOL TRINITRATE	D		
55-63-0		NITRO MACK	S		
55-63-0		NITRO PRN	S		
	2-	NITRO-2-METHYLPROPANOL NITRATE	D		
	6-	NITRO-4-DIAZOTOLUENE-3-SULFONIC ACID (DRY)	D		
1514-52-9	4-	NITROBENZENE DIAZONIUM HEXAFLUOROPHOSPHATE	T	W	
	M-	NITROBENZENE DIAZONIUM PERCHLORATE	D		
456-27-9	P-	NITROBENZENE DIAZONIUM TETRAFLUOROBORATE	S	W	
2338-12-7	5-	NITROBENZOTRAZOLE	S		
2338-12-7	5-	NITROBENZOTRIAZOL	S		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
2733-41-7	P-	NITROBENZOYL AZIDE	S		
55-63-0		NITRO-BID	S		
10124-37-5		NITROCALCITE	O		
9004-70-0		NITROCELLULOSE (DRY)	S		
		NITROCELLULOSE (IN SOLVENT <55% NITROCELLULOSE)	S		
9004-70-0		NITROCELLULOSE (WET >25% ALCOHOL)	S		
9004-70-0		NITROCELLULOSE (WET >25% WATER)	S		
9004-70-0		NITROCOTTON (DRY)	S		
9004-70-0		NITROCOTTON (WET >25% WATER)	S		
55-63-0		NITRO-DISC	S		
79-24-3		NITROETHANE	S		
		NITROETHYL NITRATE	D		
		NITROETHYLENE POLYMER	D		
534-52-1		NITROFAN	S		
517-25-9		NITROFORM	D		
156-62-7		NITROGEN LIME	W		
10025-85-1		NITROGEN TRICHLORIDE	D		
13444-85-4		NITROGEN TRIIODIDE	D		
		NITROGEN TRIIODIDE MONOAMINE	D		
55-63-0		NITROGLIN	S		
		NITROGLYCERIN, LIQUID, NOT DESENSITIZED	D		
		NITROGLYCERIN, SOLUTION IN ALCOHOL (1-5% NITROGLYCERIN)	S		
55-63-0		NITROGLYCERINE SOLUTION (<1% IN ALCOHOL)	S		
55-63-0		NITROGLYCERINE SPIRITS (5-10% IN ALCOHOL)	S		
55-63-0		NITROGLYCERINE, DESENTIZED WITH NOT LESS THAN 40% NON-VOLATILE WATER INSOLUBLE PHLEGMATIZER, BY	S		
55-63-0		NITROGLYCEROL	S		
628-96-6		NITROGLYCOL	D		
556-88-7		NITROGUANIDINE (DRY)	S		
556-88-7		NITROGUANIDINE (WET >20% WATER)	S		
		NITROGUANIDINE NITRATE	D		
13373-32-5		NITROIMIDE	S		
55-63-0		NITROLAN	S		
55-63-0		NITROLAR	S		
55-63-0		NITRO-LENT	S		
55-63-0		NITROLETTEN	S		
156-62-7		NITROLIM	W		
156-62-7		NITROLIME	W		
55-63-0		NITROLINGUAL	S		
55-63-0		NITROLOWE	S		
15825-70-4		NITROMANNITE (DRY)	D		
15825-70-4		NITROMANNITE (WET >40% WATER)	S		
15825-70-4		NITROMANNITOL	S		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
55-63-0		NITROMEL	S		
75-52-5		NITROMETHANE	S		
55-63-0		NITRONAL	S		
		NITRONAPHTHALENE	S		
55-63-0		NITRONG	S		
13826-86-3		NITRONIUM TETRAFLUOROBORATE	W		
		NITRO-N-METHYLGLYCOLAMIDE NITRATE	D		
78-11-5		NITROPENTA (DRY)	D		
74-39-5	4-(P-	NITROPHENYLAZO)RESORCINOL	S		
		NITROPHENYLDINITRO METHANE	D		
100-16-3	P-	NITROPHENYLHYDRAZINE	S		
88-85-7		NITROPONE C	S		
55-63-0		NITRORECTAL	S		
55-63-0		NITRORETARD	S		
	I-	NITROSO-3,5-DINITRO-1,3,5-TRIAZACYCLOHEXANE (DISSOLVE IN A 1% SOLUTION OF SOLVENT)	S		
138-89-6	P-	NITROSODIMETHYLANILINE	A		
14293-70-0		NITROSODISULFONIC ACID,DIPOTASSIUM SALT	A	W	
556-88-7		NITROSOGUANIDINE	S		
684-93-5	N-	NITROSOMETHYL UREA	T		
14653-75-7		NITROSONIUM TETRAFLUOROBORATE	W		
684-93-5	N-	NITROSO-N-METHYLUREA	T		
637-62-7	P-	NITROSOPHENOL	T		
55-63-0		NITRO-SPAN	S		
55-63-0		NITROSTABILIN	S		
9056-38-6		NITROSTARCH (DRY)	S		
9056-38-6		NITROSTARCH (WET >20% WATER)	S		
55-63-0		NITROSTAT	S		
		NITROSUGARS (DRY)	D		
14653-75-7		NITROSYL BOROFUORIDE	W		
109-95-5		NITROSYL ETHOXIDE	S	T	
14653-75-7		NITROSYL FLUOROBORATE	W		
7782-78-7		NITROSYL SULFURIC ACID	W	T	
14653-75-7		NITROSYL TETRAFLUOROBORATE	W		
		NITROTRIAZOLONE	S		
556-89-8		NITROUREA (DRY)	S		
109-95-5		NITROUS ACID ETHYL ETHER	S	T	
17861-62-0		NITROUS ACID NICKEL SALT	O		
7632-00-0		NITROUS ACID SODIUM SALT	O		
88-89-1		NITROXANTHIC ACID (WET > 30% WATER)	S		
88-89-1		NITROXANTHIC ACID (DRY)	S		
55-63-0		NITROZELL RETARD	S		
7697-37-2		NITRYL HYDROXIDE (40% OR LESS)	O		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
7697-37-2		NITRYL HYDROXIDE (OVER 40%)	O		
55-63-0		NK 843	S		
684-93-5		NMM	T		
684-93-5		NMU	T		
37187-22-7		NOROX AZOX	T		
55-63-0		NOTROL	S		
75-77-4		NSC 15750	W		
88-85-7		NSC 202753	S		
7758-01-2		NSC 215200	O		
684-93-5		NSC 23909	T		
126-98-7		NSC 24145	D		
75-79-6		NSC 77069	W	A	
75-78-5		NSC 77070	A	W	
7632-00-0		NSC 77391	O		
107-02-08		NSC 8819 (POISON INHALATION HAZARD	D		
		NTO	S		
55-63-0		NYSCONITRINE	S		
3238-27-5		OADC	A	W	
	1,7-	OCTADIENE-3,5-DIYNE-1,8-DIMETHOXY-9-OCTADECYNOIC ACID	D		
2691-41-0		OCTOGEN (DRY)	S		
2691-41-0		OCTOGEN (WET >15% WATER)	S		
		OCTOL	S		
		OCTOLITE, DRY OR WETTED WITH LESS THAN 15% WATER, BY MASS	S		
2499-59-4		OCTYL ACRYLATE	D		
123-05-7		OCTYL ALDEHYDE	A		
2157-01-9		OCTYL METHACRYLATE	D		
3238-27-5	N-	OCTYLALUMINUM DICHLORIDE	A	W	
		OCTYLLITHIUM	A	W	
38841-98-4		OCTYLMAGNESIUM CHLORIDE (IN SOLVENT)	W		
8014-95-7		OLEUM (FUMING SULFURIC ACID) (POISIN INHALATION HAZARD)	W		
101-25-7		OPEX	T		
10326-21-3		ORTHO MC	O		
79-37-8		OXALYL CHLORIDE	W		
359-40-0		OXALYL FLUORIDE	W		
7803-49-8		OXAMMONIUM	A		
110-80-5		OXITOL	D		
110-00-9		OXOLE	D		
108-60-1	2,2-	OXYBIS (2-CHLOROPROPANE)	D		
60-29-7	1,1-	OXYBIS ETHANE	D		
111-44-4	1,1'-	OXYBIS(2-CHLOROETHANE)	D		
108-20-3	2,2'-	OXYBIS(PROPANE)	D		
542-88-1		OXYBIS{CHLOROMETHANE}	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
111-43-3	1,1'-	OXYBISPROPANE	D		
1609-47-8		OXYDIFORMIC ACID DIETHYL ESTER	W		
7783-41-7		OXYGEN DIFLUORIDE (POISON INHALATION HAZARD)	A	W	D
7783-41-7		OXYGEN FLUORIDE (POISON INHALATION HAZARD)	A	W	D
302-01-2		OXYTREAT 35	S		
9004-70-0		PARLODION (WET >25% WATER)	S		
		PB/PA-TPE	S		
3811-04-9		PEARL ASH	O		
3811-04-9		PEARL ASH SOLUTION	O		
80-62-6		PEGALAN	D		
78-11-5		PENCARD (DRY)	D		
40487-42-1		PENDIMETHALIN	S		
40487-42-1		PENDIMETHALINE	S		
40487-42-1		PENOXALIN	S		
19624-22-7		PENTABORANE (POISON INHALATION HAZARD)	A		
19624-22-7		PENTABORON NONAHYDRIDE (9) (POISON INHALATION HAZARD)	A		
13463-40-6		PENTACARBONYL IRON (POISON INHALATION HAZARD)	A		
78-11-5		PENTAERYTHRITE TETRANITRATE (DRY)	D		
78-11-5		PENTAERYTHRITE TETRANITRATE (WET >25% WATER)	S		
78-11-5		PENTAERYTHRITE TETRANITRATE, DESENSITIZED, WET, WITH GREATER THAN 7% WAX	S		
78-11-5		PENTAERYTHRITOL TETRANITRATE (DRY)	D		
78-11-5		PENTAERYTHRITOL TETRANITRATE (WET >25% WATER)	S		
78-11-5		PENTAFIN (DRY)	D		
7783-66-6		PENTAFLUOROIODINE	W		
142-68-7		PENTAMETHYLENE OXIDE	D		
37187-22-7	2,4-	PENTANEDIONE PEROXIDE, <=32% AS A PASTE	T		
37187-22-7	2,4-	PENTANEDIONE PEROXIDE, <=42%	T		
37187-22-7	2,4-	PENTANEDIONE PEROXIDE, >42%	T	S	
21958-87-5		PENTANITROANILINE (DRY)	D		
78-11-5		PENTESTAN-80 (DRY)	D		
		PENTOLITE (DRY OR <15% WATER)	S		
78-11-5		PENTRATE (DRY)	D		
78-11-5		PENTRIOL (DRY)	D		
693-65-2		PENTYL ETHER	D		
40487-42-1	N-(3-	PENTYL)-3,4-DIMETHYL-2,6-DINITROANILINE	S		
693-25-4		PENTYLMAGNESIUM BROMIDE (IN DIETHYL ETHER)	W		
79-21-0		PER ACID, >43%	T	S	
79-21-0		PER ACID, TYPE D, STABILIZED, <=43%	T		
79-21-0		PERACETIC ACID, >43%	T	S	
79-21-0		PERACETIC ACID, TYPE D, STABILIZED, <=43%	T		
124-43-6		PERCARBAMIDE	T		
7778-74-7		PERCHLORACAP	O	S	

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
7616-83-3		PERCHLORIC ACID MERCURY II SALT, HYDRATE	O	S	
7790-98-9		PERCHLORIC ACID, AMMONIUM SALT	O	S	
7601-90-3		PERCHLORIC ACID, EXCEEDING 50% BUT NOT EXCEEDING 72% STRENGTH	O		
7601-90-3		PERCHLORIC ACID, EXCEEDING 72% STRENGTH	D		
7601-90-3		PERCHLORIC ACID, NOT OVER 50% ACID	O		
55-63-0		PEREUTOL	S		
10036-47-2		PERFLUORO HYDRAZINE (POISON INHALATION HAZARD)	S	T	
116-14-3		PERFLUOROETHYLENE, INHIBITED	D		
55-63-0		PERGLOTTEN	S		
10450-60-9		PERIODIC ACID	O		
87413-09-0		PERIODINANE	S	T	
78-11-5		PERITRATE (DRY)	D		
		PERKADOX 12-AEZO	T		
25155-25-3		PERKADOX 14	T		
25155-25-3		PERKADOX 14S	T		
15520-11-3		PERKADOX 16	T		
15520-11-3		PERKADOX 16S	T		
15520-11-3		PERKADOX 16-W40	T		
15520-11-3		PERKADOX 16-W70	T		
6731-36-8		PERKADOX 29-B75	T		
		PEROCTOATE-20H	T		
		PEROCTOATE-MC20	T		
7778-74-7		PEROIDIN	O	S	
5796-98-5		PEROXIDE CURING AGENT	T		
80-43-3		PEROXIMON DC	T		
80-43-3		PEROXIMON DC/SC	T		
25155-25-3		PEROXIMON F	T		
1338-23-4		PEROXIMON K10	T		
37187-22-7		PEROXIMON K3	T		
79-21-0		PEROXYACETIC ACID, >43%	T	S	
79-21-0		PEROXYACETIC ACID, TYPE D, STABILIZED, <=43%	T		
78-11-5		PETN (DRY)	D		
78-11-5		PETN (WET >25% WATER)	S		
100-42-5		PHENETHYLENE, INHIBITED	D		
103-73-1		PHENETOLE	D		
88-89-1		PHENOLTRINITRATE (DRY)	S		
40487-42-1		PHENOXALIN	S		
100-42-5		PHENTLETHENE, INHIBITED	D		
103-73-1		PHENYL ETHYL ETHER	D		
122-60-1		PHENYL GLYCIDYL ETHER	D		
591-51-5		PHENYL LITHIUM (IN CYCLOHEXANE-ETHER)	A	W	
768-33-2		PHENYLDIMETHYLCHLOROSILANE	A		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
		PHENYLENE DIAMINEDIPERCHLORATE (DRY)	D		
100-42-5		PHENYLETHYLENE, INHIBITED	D		
100-58-3		PHENYLMAGNESIUM BROMIDE (IN SOLVENT)	W		
100-59-4		PHENYLMAGNESIUM CHLORIDE (IN SOLVENT)	W		
98-82-8	2-	PHENYLPROPANE	D		
98-83-9	2-	PHENYLPROPENE	D		
1314-56-3		PHOSPHORIC ACID, ANHYDROUS	W		
1314-56-3		PHOSPHORIC ANHYDRIDE	W		
10026-13-8		PHOSPHORIC CHLORIDE	W		
1314-56-3		PHOSPHORIC OXIDE	W		
10026-13-8		PHOSPHORIC PERCHLORIDE	W		
1314-80-3		PHOSPHORIC SULFIDE	W		
		PHOSPHORUS (WHITE OR RED) AND A CHLORATE MIX	D		
7719-12-2		PHOSPHORUS CHLORIDE (POISON INHALATION HAZARD)	W		
10026-13-8		PHOSPHORUS PENTACHLORIDE	W		
1314-80-3		PHOSPHORUS PENTASULFIDE	W		
1314-56-3		PHOSPHORUS PENTOXIDE	W		
1314-80-3		PHOSPHORUS PERSULFIDE	W		
1314-85-8		PHOSPHORUS SESQUISULFIDE	W		
1314-80-3		PHOSPHORUS SULFIDE	W		
7719-12-2		PHOSPHORUS TRICHLORIDE (POISON INHALATION HAZARD)	W		
7723-14-0		PHOSPHORUS WHITE, DRY OR IN WATER	A		
7723-14-0		PHOSPHORUS WHITE, MOLTEN	A		
7723-14-0		PHOSPHORUS YELLOW, DRY OR IN WATER	A		
7723-14-0		PHOSPHORUS, AMORPHOUS, RED	A	W	
7723-14-0		PHOSPHORUS-31	A		
20859-73-8		PHOSTOXIN (A)	W		
1305-99-3		PHOTOPHOR	W		
108-60-1		PICHLORAM	D		
88-89-1		PICRAL (DRY)	S		
88-89-1		PICRAL (WET > 30% WATER)	S		
96-91-3		PICRAMIC ACID (WET)	S		
831-52-7		PICRAMIC ACID, SODIUM SALT (DRY)	S		
831-52-7		PICRAMIC ACID, SODIUM SALT (WET >20% WATER)	S		
489-98-5		PICRAMIDE	S		
96-91-3		PICRAMINIC ACID (WET)	S		
88-89-1		PICRIC ACID (DRY)	S		
88-89-1		PICRIC ACID (WET >30% WATER)	S		
556-88-7		PICRITE (DRY)	S		
556-88-7		PICRITE (WET >20% WATER)	S		
88-89-1		PICRONITRIC ACID (WET > 30% WATER)	S		
88-89-1		PICRONITRIC ACID, (DRY)	S		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
28260-61-9		PICRYL CHLORIDE	S		
28930-30-5		PICRYL SULFIDE (DRY)	S		
28930-30-5		PICRYL SULFIDE (WET >10% WATER)	S		
2508-19-2		PICRYLSULFONIC ACID	S		
		PINANYL HYDROPEROXIDE, <56%	T		
		PINANYL HYDROPEROXIDE, 56-100%	T		
12427-38-2		PLANTIFOG 160M	W		
		POLY BAMO-POLY AMMO THERMOPLASTIC ELASTOMOER	S		
		POLY OXETANE THERMOPLASTIC BINDER	S		
12427-38-2		POLYRAM M	W		
110-80-5		POLY-SOLV EE	D		
109-86-4		POLY-SOLV EM	D		
7440-09-7		POTASSIUM	W		
13455-24-8		POTASSIUM BIODATE	O		
13762-51-1		POTASSIUM BOROHYDRIDE	W		
7758-01-2		POTASSIUM BROMATE	O		
3811-04-9		POTASSIUM CHLORATE	O		
3811-04-9		POTASSIUM CHLORATE, SOLUTION	O		
12030-88-5		POTASSIUM DIOXIDE	W		
		POTASSIUM DITHIONITE	A		
917-58-8		POTASSIUM ETHOXIDE	W		
7693-26-7		POTASSIUM HYDRIDE	W		
13455-24-8		POTASSIUM HYDROGEN DIODATE	O		
		POTASSIUM HYDROSULFITE	A		
7758-05-6		POTASSIUM IODATE	O		
7790-21-8		POTASSIUM METAPERIODATE	O		
865-33-8		POTASSIUM METHOXIDE	W		
1312-73-8		POTASSIUM MONOSULFIDE	A		
7757-79-1		POTASSIUM NITRATE	O		
7758-09-0		POTASSIUM NITRITE	O		
14293-70-0		POTASSIUM NITROSODISULFONATE	A	W	
3811-04-9		POTASSIUM OXYMURIATE	O		
3811-04-9		POTASSIUM OXYMURIATE SOLUTION	O		
7778-74-7		POTASSIUM PERCHLORATE	O	S	
7790-21-8		POTASSIUM PERIODATE	O		
17014-71-0		POTASSIUM PEROXIDE	W		
20770-41-6		POTASSIUM PHOSPHIDE	W		
11135-81-2		POTASSIUM SODIUM ALLOY	W		
1312-73-8		POTASSIUM SULFIDE (<30% WATER)	A		
1312-73-8		POTASSIUM SULFIDE, ANHYDROUS	A		
12030-88-5		POTASSIUM SUPEROXIDE	W		
7440-09-7		POTASSIUM, METAL ALLOYS	W		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
41233-93-6		POTASSIUM-T-AMYLATE, 25% IN TOLUENE	W		
865-47-4		POTASSIUM-T-BUTOXIDE	A		
865-47-4		POTASSIUM-T-BUTYLATE	A		
54575-50-7		POTASSIUM-TRI-SEC-BUTYLBOROHYDRIDE (IN DIETHYL ETHER)	A	W	
88-85-7		PREMERGE 3	S		
534-52-1		PROKARBOL	S		
107-02-08		PROP-2-EN-1-AL (POISON INHALATION HAZARD)	D		
55-63-0		PROPANETRIOL TRINITRATE	S		
55-63-0	1,2,3-	PROPANETRYL NITRATE	S		
107-02-08		PROPENAL (POISON INHALATION HAZARD)	D		
107-02-08		PROPENALDEHYDE (POISON INHALATION HAZARD)	D		
107-13-1		PROPENENITRILE	D		
107-13-1	2-	PROPENENITRILE	D		
79-10-7		PROPENOIC ACID	D		
79-10-7	2-	PROPENOIC ACID	D		
140-88-5	2-	PROPENOIC ACID ETHYL ESTER	D		
140-88-5	2	PROPENOIC ACID ETHYL ESTER	D		
96-33-3	2-	PROPENOIC ACID METHYL ESTER	D		
141-32-2	2-	PROPENOIC ACID, BUTYL ESTER	D		
140-88-5	1	PROPENOIC ACID,ETHYL ESTER	D		
814-68-6	2-	PROPENOYL CHLORIDE	D		
105-37-3		PROPIONIC ETHER	D		
111-43-3		PROPYL ETHER	D		
107-98-2	1-	PROPYLENE GLYCOL METHYL ETHER	D		
75-55-8		PROPYLENEIMINE,INHIBITED	D		
75-55-8		PROPYLENIMINE	D		
75-55-8	1,2-	PROPYLENIMINE	D		
2234-82-4	N-	PROPYLMAGNESIUM CHLORIDE (2.0M IN DIETHYL ETHER)	W		
74-99-7		PROPYNE	D		
40487-42-1		PROWL	S		
74-90-8		PRUSSIC ACID, ANHYDROUS, STABILIZED (PIH)	S		
95-63-6		PSEUDOCUMENE	D		
95-63-6		PSEUDOCUMOL	D		
10049-04-4		PUROGENE	S		
		P-XYLYL DIAZIDE	D		
		PYRIDINE PERCHLORATE	D		
110-51-0		PYRIDINEBORANE	W		
1609-47-8		PYROCARBONIC ACID DIETHYL ESTER	W		
91-16-7		PYROCATECHOL DIMETHYL ETHER	D		
7791-27-7		PYROSULFURYL CHLORIDE	W		
9004-70-0		PYROXYLIN (DRY)	S		
9004-70-0		PYROXYLIN (WET >25% WATER)	S		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
		PYROXYLIN PLASTIC, RODS, SHEETS, ROLLS, OR TUBES	S		
106-99-0		PYRROLYLENE	D		
105-11-3		QDO	S		
		QUEBRACHITOL PENTANITRATE	D		
20859-73-8		QUICKPHOS	W		
105-11-3	P-	QUINONE DIOXINE	S		
534-52-1		RAFEX (35)	S		
7440-02-0		RANEY NICKEL (WET)	A		
534-52-1		RAPHATOX	S		
7723-14-0		RAT-NIP	A		
121-82-4		RDX (WET >15% WATER)	S		
121-82-4		RDX, DESENSITIZED	S		
22722-98-1		RED ALUMINUM (IN SOLVENT)	W		
22722-98-1		RED-AL (IN SOLVENT)	W		
151-10-0		RESORCINOL DIMETHYL ETHER	D		
10049-17-9		RHENIUM (VI) FLUORIDE	W		
12595-06-1		RHENIUM HEPTASULFIDE	A		
10049-17-9		RHENIUM HEXAFLUORIDE	W		
12427-38-2		RHODIANEBE	W		
7440-17-7		RUBIDIUM	W		
101-68-8		RUBINATE 44	W		
605-69-6		SAFFRON YELLOW	S		
3811-04-9		SALT OF TARTAR	O		
3811-04-9		SALT OF TARTAR SOLUTION	O		
7757-79-1		SALTPETER	O		
534-52-1		SANDOLIN (A)	S		
70-34-8		SANGER'S REAGENT	S		
38721-52-7	L-	SELECTRIDE (IN THF)	A	W	
12033-59-9		SELENIUM NITRIDE	D		
534-52-1		SELINON	S		
		SIGNAL DEVICES, HAND	S		
		SIGNALS, SMOKE	S		
7803-62-5		SILANE	A	W	
75-77-4		SILANE, CHLOROTRIMETHYL	W		
75-77-4		SILICANE, CHLOROTRIMETHYL	W		
10025-78-2		SILICOCHLOROFORM	W		
10026-04-7		SILICON CHLORIDE	W		
10026-04-7		SILICON TETRACHLORIDE	W		
7803-62-5		SILICON TETRAHYDRIDE	A	W	
133-14-2		SILOPRENE CL40	T		
12092-75-6		SILVER ACETYLIDE (DRY)	D		
13863-88-2		SILVER AZIDE (DRY)	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
7783-92-8		SILVER CHLORATE	O	S	
7783-91-7		SILVER CHLORITE (DRY)	D		
5610-59-3		SILVER FULMINATE (DRY)	S		
7761-88-8		SILVER NITRATE	O		
533-51-7		SILVER OXALATE (DRY)	D		
146-84-9		SILVER PICRATE (DRY)	D		
534-52-1		SINOX	S		
88-85-7		SINOX GENERAL	S		
26628-22-8		SMITE	S	T	
		SMOKELESS POWDER FOR SMALL ARMS (<100 LBS)	S		
7775-09-9		SODA CHLORATE	O		
7631-99-4		SODA NITER	O		
7782-92-5		SODAMIDE	S	W	A
7440-23-5		SODIUM	W	A	
17836-88-3		SODIUM ALUMINUM DIETHYL DIHYDRIDE (2.0M IN TOLUENE)	A	W	
13770-96-2		SODIUM ALUMINUM HYDRIDE	W		
11110-52-4		SODIUM AMALGAM	W		
7782-92-5		SODIUM AMIDE	S	W	A
26628-22-8		SODIUM ARDE	S	T	
26628-22-8		SODIUM AZIDE	S	T	
22722-98-1		SODIUM BIS(2-METHOXYETHOXY)ALUMINUM HYDRIDE	W		
1070-89-9		SODIUM BIS(TRIMETHYLSILYL) AMIDE	W		
16721-80-5		SODIUM BISULFIDE, SOLID (<25% WATER OF CRYSTALLIZATION)	A		
25895-60-7		SODIUM BOROCYANOHYDRIDE	W		
16940-66-2		SODIUM BOROHYDRIDE	W		
7789-38-0		SODIUM BROMATE	O		
7775-09-9		SODIUM CHLORATE	O		
7775-09-9		SODIUM CHLORATE, SOLUTION	O		
7758-19-2		SODIUM CHLORITE	O		
7758-19-2		SODIUM CHLORITE, SOLUTION	O		
25895-60-7		SODIUM CYANOBOROHYDRIDE	W		
25895-60-7		SODIUM CYANOHYDRIDOBORATE	W		
25895-60-7		SODIUM CYANOTRIHYDRIDOBORATE	W		
17836-88-3		SODIUM DIETHYLDIHYDROALUMINATE(2.0M IN TOLUENE)	A	W	
25641-53-6		SODIUM DINITRO-O-CRESOLATE (DRY)	S		
25641-53-6		SODIUM DINITRO-O-CRESOLATE (WET >15% WATER)	S		
1313-60-6		SODIUM DIOXIDE	W	O	
7775-14-6		SODIUM DITHIONITE	A		
141-52-6		SODIUM ETHOXIDE	W		
141-52-6		SODIUM ETHYLATE	W		
7646-69-7		SODIUM HYDRIDE	W		
16721-80-5		SODIUM HYDROGEN SULFIDE, SOLID (<25% WATER OF CRYSTALLIZATION)	A		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
16721-80-5		SODIUM HYDROSULFIDE (<25% WATER OF CRYSTALLIZATION)	A		
7775-14-6		SODIUM HYDROSULFITE	A		
7681-55-2		SODIUM IODATE	O		
12740-44-2		SODIUM LEAD ALLOY	W		
7440-23-5		SODIUM METAL LIQUID ALLOY	W	A	
7790-28-5		SODIUM METAPERIODATE	O		
124-41-4		SODIUM METHOXIDE, DRY	A	W	
124-41-4		SODIUM METHYLATE	A	W	
1313-82-2		SODIUM MONOSULFIDE	A	W	
1313-59-3		SODIUM MONOXIDE	W		
7631-99-4		SODIUM NITRATE	O		
7632-00-0		SODIUM NITRITE	O		
		SODIUM NITRITE, MIXED (FUSED) W/POTASSIUM NITRATE	O		
1313-59-3		SODIUM OXIDE, 86% ASSAY	W		
7601-89-0		SODIUM PERCHLORATE	O	S	
7790-28-5		SODIUM PERIODATE	O		
1313-60-6		SODIUM PEROXIDE	W	O	
12058-85-4		SODIUM PHOSPHIDE	W		
831-52-7		SODIUM PICRAMATE (DRY)	S		
831-52-7		SODIUM PICRAMATE (WET >20% WATER)	S		
		SODIUM PICRYL PEROXIDE	D		
11135-81-2		SODIUM POTASSIUM ALLOY	W		
16721-80-5		SODIUM SULFHYDRATE, SOLID (<25% WATER OF CRYSTALLIZATION)	A		
1313-82-2		SODIUM SULFIDE (<30% WATER OF CRYSTALLIZATION)	A	W	
1313-82-2		SODIUM SULFIDE, ANHYDROUS(WITH<30% WATER OF CRYSTALLIZATION)	A	W	
7775-14-6		SODIUM SULFOXYLATE	A		
1313-82-2		SODIUM SULFURET, ANHYDROUS	A	W	
12034-12-7		SODIUM SUPEROXIDE	W	O	
16940-66-2		SODIUM TETRAHYDRIDOBORATE	W		
		SODIUM TETRANITRIDE	D		
5188-07-8		SODIUM THIOMETHOXIDE	W		
56553-60-7		SODIUM TRIACETOXYBOROHYDRIDE	W		
1313-60-6		SOLOZONE	W	O	
88-85-7		SPARIC	S		
109-95-5		SPIRIT OF ETHYL NITRITE	S	T	
55-63-0		SPIRITS OF NITROGLYCERINE (<1% NITROGLYCERIN IN ALCOHOL)	S		
88-85-7		SPURGE	S		
25324-56-5		STANNIC PHOSPHIDE	W		
9056-38-6		STARCH NITRATE (DRY)	S		
9056-38-6		STARCH NITRATE (WET >20% WATER)	S		
40487-42-1		STOMP (330; 330E; 330D)	S		
7791-10-8		STRONTIUM CHLORATE	O		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
1314-18-7		STRONTIUM DIOXIDE	W	O	
7440-24-6		STRONTIUM METAL	W		
10042-76-9		STRONTIUM NITRATE	O		
13450-97-0		STRONTIUM PERCHLORATE	O		
1314-18-7		STRONTIUM PEROXIDE	W	O	
12504-13-1		STRONTIUM PHOSPHIDE	W		
82-71-3		STYPHNIC ACID (DRY)	S		
82-71-3		STYPHNIC ACID (WET >20% WATER)	S		
100-42-5		STYRENE MONOMER, INHIBITED	D		
100-42-5		STYROL, INHIBITED	D		
100-42-5		STYROLE, INHIBITED	D		
100-42-5		STYROLENE, INHIBITED	D		
100-42-5		STYROPOL SO, INHIBITED	D		
123-23-9		SUCCINIC ACID PEROXIDE, <=72% WITH 28% WATER	T		
123-23-9		SUCCINIC ACID PEROXIDE, >72-100%	T		
543-20-4		SUCCINYL CHLORIDE	W		
30236-29-4		SUCROSE OCTANITRATE (DRY)	D		
		SULFUR AND CHLORATE (LOOSE MIXTURES OF)	D		
10545-99-0		SULFUR CHLORIDE (DI)(POISON INHALATION HAZARD)	W		
10025-67-9		SULFUR CHLORIDE (MONO) (POISON INHALATION HAZARD)	W		
10545-99-0		SULFUR DICHLORIDE (POISON INHALATION HAZARD)	W		
10025-67-9		SULFUR MONOCHLORIDE (MONO) (POISON INHALATION HAZARD)	W		
7719-09-7		SULFUR OXYCHLORIDE (POISON INHALATION HAZARD)	W		
10025-67-9		SULFUR SUBCHLORIDE (MONO) (POISON INHALATION HAZARD)	W		
8014-95-7		SULFURIC ACID, FUMING >=30% FREE SULFUR TRIOXIDE (PIH)	W		
7719-09-7		SULFUROUS OXYCHLORIDE (POISON INHALATION HAZARD)	W		
1314-80-3		SULPHUR PHOSPHIDE	W		
22560-16-3		SUPER HYDRIDE (IN THF)	W		
1338-23-4		SUPEROX 702	T		
1338-23-4		SUPEROX 732	T		
94-36-0		SUPEROX 742	T		
94-36-0		SUPEROX 744	T		
55-63-0		SUSCARD	S		
55-63-0		SUSTAC	S		
109-95-5		SWEET SPIRIT OF NITRE	S	T	
7632-00-0		SYNFAT 1004	O		
4262-43-5		TBA (POISON INHALATION HAZARD)	A		
122-56-5	01	TBB	A		
75-91-2		TBHP-70	T		
2501-94-2		TBP (POISON INHALATION HAZARD)	A		
97-93-8		TEA	A	W	
1722-26-5		TEAB	W		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
97-94-9		TEB	A		
923-34-2		TEI	A	W	
593-80-6		TELLURIDE, DIMETHYL	A	W	
55-63-0		TEMONITRIN	S		
40487-42-1		TENDIMETHALIN	S		
13071-79-9		TERBUFOS	W		
4262-43-5		TERTIARYBUTYLARSINE (POISON INHALATION HAZARD)	A		
2501-94-2		TERTIARYBUTYLPHOSPHINE (POISON INHALATION HAZARD)	A		
22826-61-5		TETRAAZIDO BENZENE QUINONE	D		
33725-74-5		TETRABUTYL AMMONIUM BOROHYDRIDE	W		
13463-39-3		TETRACARONYL NICKEL	A		
10026-04-7		TETRACHLOROSILANE	W		
10026-04-7		TETRACHLOROSILICON	W		
7550-45-0		TETRACHLOROTITANIUM (POISON INHALATION HAZARD)	A	W	
2567-83-1		TETRAETHYLAMMONIUM PERCHLORATE (DRY)	S		
17831-71-9		TETRAETHYLENE GLYCOL DIACRYLATE	D		
116-14-3		TETRAFLUOROETHYLENE, INHIBITED	D		
10036-47-2		TETRAFLUOROXYDRAZINE (POISON INHALATION HAZARD)	S	T	
696-59-3		TETRAHYDRO-2,5-DIMETHOXYFURAN	D		
96-47-9		TETRAHYDRO-2-METHYLFURAN	D		
110-83-8	1234-	TETRAHYDROBENZENE	D		
109-99-9		TETRAHYDROFURAN	D		
119-64-2		TETRAHYDRONAPHTHALENE	D		
		TETRAHYDRONAPHTHYL HYDROPEROXIDE, <=100%	T		
142-68-7		TETRAHYDROPYRAN	D		
998-00-5		TETRAISOBUTYLDIALUMINOXANE	A		
4419-47-0		TETRAKIS (DIETHYLAMINO) TITANIUM	W		
12386-10-6		TETRAMETHYLAMMONIUM HYDROTRIBORATE	W		
12386-10-6		TETRAMETHYLAMMONIUM OCTAHYDROTRIBORATE	W		
2537-36-2		TETRAMETHYLAMMONIUM PERCHLORATE	S		
3676-91-3		TETRAMETHYLBIPHOSPHINE	A	W	
	1133-	TETRAMETHYLBUTYL HYDROPEROXIDE, <=100%	T		
	1,1,3,3,-	TETRAMETHYLBUTYL PEROXY-2-ETHYLHEXANOATE, <=100%	T		
2082-81-7		TETRAMETHYLENE DIACRYLATE	D		
		TETRAMETHYLENE DIPEROXIDE DICARBIMIDE	D		
75-76-3		TETRAMETHYLSILANE	A		
993-22-6		TETRA-N-BUTYLAMMONIUM AZIDE	S		
3698-54-2		TETRANITROANILINE	S		
42798-98-1		TETRANITROBLUE TETRAZOLIUM	S		
20600-96-8		TETRANITRODIGLYCERIN	D		
509-14-8		TETRANITROMETHANE (POISON INHALATION HAZARD)	O	S	
641-16-7	2346-	TETRANITROPHENOL	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
	2346-	TETRANITROPHENYL METHYL NITRAMINE	D		
	2346-	TETRANITROPHENYLNITRAMINE	D		
		TETRANITRORESORCINOL (DRY)	D		
	2356-	TETRANITROSO NITROBENZENE (DRY)	D		
	2356-	TETRANITROSO-1,4-DINITROBENZENE	D		
1314-85-8		TETRAPHOSPHOROUS TRISULFIDE	W		
3087-37-4		TETRAPROPYL ORTHOTITANATE	A	W	
15780-02-6		TETRAPROPYLAMMONIUM PERCHLORATE	O	S	
109-27-3		TETRAZENE (DRY)	D		
109-27-3		TETRAZENE (WET >30% WATER)	S		
27120-23-6		TETRAZINE (DRY)	D		
		TETRAZOL-1-ACETIC ACID	S		
288-94-8	IH-	TETRAZOLE	S		
		TETRAZOYL AZIDE (DRY)	D		
110-00-9		TETROL	D		
479-45-8		TETRYL	S		
13453-30-0		THALLIUM CHLORATE	O		
10102-45-1		THALLIUM NITRATE	O		
10102-45-1		THALLOUS NITRATE	O		
109-99-9		THF	D		
463-56-9		THIOCYANIC ACID (POLYMERIZATION HAZARD)	D		
7719-09-7		THIONYL CHLORIDE	W		
1314-80-3		THIOPHOSPHORIC ANHYDRIDE	W		
100-99-2		TIBAL	A	W	
1116-39-8		TIBB	A	W	
		TIN CATALYST	A		
25324-56-5		TIN PHOSPHIDE	W		
7550-45-0		TITANIC CHLORIDE (POISON INHALATION HAZARD)	A	W	
7550-45-0		TITANIUM (IV) CHLORIDE (POISON INHALATION HAZARD)	A	W	
10049-06-6		TITANIUM DICHLORIDE	A		
3087-36-4		TITANIUM ETHOXIDE	W		
7704-98-5		TITANIUM HYDRIDE	W		
7440-32-6		TITANIUM METAL POWDER, DRY OR WET WITH <20% WATER	A		
3087-37-4		TITANIUM PROPOXIDE	A	W	
7550-45-0		TITANIUM TETRACHLORIDE (POISON INHALATION HAZARD)	A	W	
4419-47-0		TITANIUM TETRAKIS (DIETHYLAMIDE)	W		
7705-07-9		TITANIUM TRICHLORIDE, PYROFORIC	A	W	
7705-07-9		TITANOUS CHLORIDE	A	W	
4419-47-0		TKDEA TI	W		
75-22-9		TMAB	W		
75-24-1		TMAL	A	W	
593-90-8		TMB	A		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
3698-54-2		TNA	S		
99-35-4		TNB (DRY)	S		
99-35-4		TNB (WET >30% WATER)	S		
1116-70-7		TNBAL	A	W	
42798-98-1		TNBT	S		
		TNHAL	A	W	
1070-00-4		TNOAL	A	W	
3248-78-0		TNOB	A	W	
118-96-7		TNT (DRY)	S		
118-96-7		TNT (WET >30% WATER)	S		
		TOE PUFFS, NITROCELLULOSE BASE	S		
932-31-0		TOLUENE MAGNESIUM BROMIDE (IN FLAMMABLE SOLVENT)	W		
33872-80-9		TOLUENE MAGNESIUM CHLORIDE (IN FLAMMABLE SOLVENT)	W		
932-31-0	O-	TOLYLMAGNESIUM BROMIDE (IN FLAMMABLE SOLVENT)	W		
33872-80-9	O-	TOLYLMAGNESIUM CHLORIDE (IN FLAMMABLE SOLVENT)	W		
		TRI-(B-NITROXYETHYL)AMMONIUM NITRATE	D		
101-37-1		TRIALLYL CYANURATE	D		
1025-15-6		TRIALLYL ISOCYANURATE	D		
1025-15-6		TRIALLYL-1,3,5-TRIAZINE-2,4,6(1H,3H,5H)-TRIONE	D		
101-37-1	2,4,6	TRIALLYLOXY-1,3,5-TRIAZINE	D		
6569-51-3	S-	TRIAZABORANE	W		
105-64-6		TRIBONOX ADC	T		
6569-51-3		TRIBORINE TRIAMINE	W		
6569-51-3		TRIBORON NITRIDE	W		
122-56-5		TRIBUTYL BORANE	A		
1116-70-7		TRIBUTYLALUMINUM	A		
122-56-5	02	TRIBUTYLBORINE	A		
6180-99-0		TRIBUTYLTIN DEUTERIDE	W		
688-73-3		TRIBUTYLTIN HYDRIDE	W		
1067-52-3		TRIBUTYLTIN METHOXIDE	W		
7446-70-0		TRICHLOROALUMINUM	W		
10294-34-5		TRICHLOROBORANE (POISON INHALATION HAZARD)	W		
10294-34-5		TRICHLOROBORON (POISON INHALATION HAZARD)	W		
		TRICHLROMETHYL PERCHLORATE	D		
75-79-6		TRICHLROMETHYLSILICON	W	A	
101-38-2	N,2,6-	TRICHLORO-P-BENZOQUINONE IMINE	T		
10025-78-2		TRICHLOROSILANE	W		
12542-85-7		TRICHLOROTRIMETHYLDIALUMINUM	A	W	
75-94-5		TRICHLOROVINYLSILANE	W		
77-73-6		TRICYCLO(5,2,1,0)-3,8-DECADIENE	D		
55-63-0		TRIDIL	S		
1115-99-7		TRIETHYL GALLIUM	A	W	

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

<i>Chemical CAS#</i>	<i>Prefix</i>	<i>Chemical Name</i>	<i>Reactive Chemical Stimulus 1</i>	<i>Reactive Chemical Stimulus 2</i>	<i>Reactive Chemical Stimulus 3</i>
554-70-1		TRIETHYL PHOSPHINE	A		
97-93-8		TRIETHYLALUMINUM	A	W	
1722-26-5		TRIETHYLAMINE BORANE	W		
554-68-7		TRIETHYLAMINE HYDROCHLORIDE			
97-94-9		TRIETHYLBORANE	A		
97-94-9		TRIETHYLBORINE	A		
1115-99-7		TRIETHYLGALLANE	A	W	
923-34-2		TRIETHYLINDIUM	A	W	
675-14-9	2,4,6-	TRIFLUORO-1,3,5-TRIAZINE	W		
110-88-3		TRIFORMOL	D		
		TRIFORMOXIME TRINITRATE	D		
78-63-7		TRIGONOX 101	T		
		TRIGONOX 113-C60	T		
		TRIGONOX 117	T		
686-31-7		TRIGONOX 121	T		
686-31-7		TRIGONOX 121-BB75	T		
		TRIGONOX 122-C80	T		
29240-17-3		TRIGONOX 123-C75	T		
29240-17-3		TRIGONOX 125-C75	T		
4511-39-1		TRIGONOX 127	T		
		TRIGONOX 131	T		
		TRIGONOX 141	T		
		TRIGONOX 145	T		
1068-27-5		TRIGONOX 14S-E85	T		
		TRIGONOX 151-C70	T		
3006-82-4		TRIGONOX 161	T		
995-33-5		TRIGONOX 17	T		
		TRIGONOX 17-40BPD	T		
3006-82-4		TRIGONOX 21	T		
3006-82-4		TRIGONOX 21-C50	T		
3006-82-4		TRIGONOX 21-C75	T		
3006-82-4		TRIGONOX 21-OP50	T		
3006-86-8		TRIGONOX 22-BB80	T		
		TRIGONOX 22-C50	T		
3006-86-8		TRIGONOX 22-E75	T		
26748-41-4		TRIGONOX 23-C75	T		
		TRIGONOX 257-C75	T		
927-07-1		TRIGONOX 25-C75	T		
6731-36-8		TRIGONOX 29	T		
6731-36-8		TRIGONOX 29-B75	T		
3851-87-4		TRIGONOX 36-C60	T		
3851-87-4		TRIGONOX 36-C75	T		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
O - Strong Oxidizing Materials
S - Shock, Friction, Static Charge
W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
P - Pressure Release (for future use)
T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
37187-22-7		TRIGONOX 40	T		
		TRIGONOX 42PR	T		
		TRIGONOX 42S	T		
37187-22-7		TRIGONOX 61	T		
		TRIGONOX 97-C75	T		
		TRIGONOX 99-C75	T		
		TRIGONOX 99-W40	T		
3179-56-4		TRIGONOX ACS-M28	T		
105-64-6		TRIGONOX ADC-NS60	T		
75-91-2		TRIGONOX A-W70	T		
110-05-4		TRIGONOX B	T		
2372-21-6		TRIGONOX BPIC	T		
614-45-9		TRIGONOX C	T		
2167-23-9		TRIGONOX D-E50	T		
1611-62-9		TRIGONOX EHP	T		
1611-62-9		TRIGONOX EHP-AT70	T		
1611-62-9		TRIGONOX EHP-C40	T		
1611-62-9		TRIGONOX EHP-C75	T		
107-71-1		TRIGONOX F-C50	T		
37206-20-5		TRIGONOX HM	T		
80-15-9		TRIGONOX K-80	T		
		TRIGONOX K-95	T		
3006-82-4		TRIGONOX KSM	T		
19910-65-7		TRIGONOX SBP	T		
19910-65-7		TRIGONOX SBP-C60	T		
3457-61-2		TRIGONOX T	T		
3425-61-4		TRIGONOX TAHP-W85	T		
		TRIGONOX TMPH-L	T		
1116-39-8		TRIISOBUTYL BORANE	A	W	
100-99-2		TRIISOBUTYLALUMINUM	A	W	
12427-38-2		TRIMANGOL	W		
12427-38-2		TRIMANGOL (80)	W		
2530-83-8		TRIMETHOXY(3-(OXIRANYMETHOXYL PROPYL) SILANE	W		
121-43-7		TRIMETHOXYBORANE	W		
121-43-7		TRIMETHOXYBORINE	W		
121-43-7		TRIMETHOXYBORON	W		
593-88-4		TRIMETHYL ARSINE	A		
121-43-7		TRIMETHYL BORATE	W		
1445-79-0		TRIMETHYL GALLIUM	A	W	
75-24-1		TRIMETHYLALUMINUM	A	W	
75-22-9		TRIMETHYLAMINE BORANE	W		
95-63-6	1,2,4-	TRIMETHYLBENZENE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure

O - Strong Oxidizing Materials

S - Shock, Friction, Static Charge

W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)

P - Pressure Release (for future use)

T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
95-63-6	1,2,5-	TRIMETHYLBENZENE	D		
95-63-6	1,3,4-	TRIMETHYLBENZENE	D		
593-90-8		TRIMETHYLBORANE	A		
593-90-8		TRIMETHYLBORINE	A		
593-90-8		TRIMETHYLBORON	A		
75-77-4		TRIMETHYLCHLOROSILANE	W		
		TRIMETHYLENE GLYCOL DIPERCHLORATE	D		
4039-32-1	1,1,1	TRIMETHYL-N (TRIMETHYLSILYL) SILANAMINE, LITHIUM SALT (1.0 M IN HEXANES)	W	A	
4039-32-1	1,1,1	TRIMETHYL-N-(TRIMETHYLSILYL) SILANAMINE LITHIUM SALT (1.0 M IN THF)	W	A	
		TRIMETHYLOL NITROMETHANE TRINITRATE	D		
15625-89-5		TRIMETHYLOL PROPANE TRIACRYLATE	D		
	2,4,4-	TRIMETHYLPENTYL-2-HYDROPEROXIDE, <=100%	T		
	2,4,4-	TRIMETHYLPENTYL-2-PEROXY PHENOXYACETATE, <=37%	T		
	2,4,4-	TRIMETHYLPENTYL-2-PEROXY-NEODECANOATE, <=52% AS A STABLE DISPERSION IN WATER	T		
	2,4,4-	TRIMETHYLPENTYL-2-PEROXY-NEODECANOATE, <=72%	T		
594-09-2		TRIMETHYLPHOSPHINE	A		
13435-12-6	N-	TRIMETHYLSILYL ACETAMIDE	W		
75-77-4		TRIMETHYLSILYL CHLORIDE	W		
7677-24-9		TRIMETHYLSILYL CYANIDE	W		
16029-98-4		TRIMETHYLSILYL IODIDE	W		
13170-43-9		TRIMETHYLSILYL METHYL MAGNESIUM CHLORIDE (IN FLAMMABLE SOLV)	W		
5796-98-5	BIS	TRIMETHYLSILYL PEROXIDE	T		
754-05-2		TRIMETHYLVINYLSILANE	W		
55-63-0		TRINALGON	S		
		TRI-N-BUTYL LITHIUM	A		
1116-70-7		TRI-N-BUTYLALUMINUM	A	W	
122-56-5		TRI-N-BUTYLBORINE	A		
6180-99-0		TRI-N-BUTYLTIN DEUTERIDE	W		
688-73-3		TRI-N-BUTYLTIN HYDRIDE	W		
1067-52-3		TRI-N-BUTYLTIN METHOXIDE	W		
		TRI-N-DECYL ALUMINUM	A	W	
		TRI-N-HEXYLALUMINUM	A	W	
55-63-0		TRINITRIN	S		
82-71-3	2,4,6-	TRINITRO-1,3-BENZENEDIOL	S		
		TRINITRO-1,3-DIAZOBENZENE	D		
81-15-2	2,4,6-	TRINITRO-1,3-DIMETHYL-5-TERT-BUTYLBENZENE	S		
129-79-3	2,4,7-	TRINITRO-9-FLUORENONE	S		
		TRINITROACETIC ACID	D		
630-72-8		TRINITROACETONITRILE	D		
		TRINITROAMINE COBALT	D		
489-98-5		TRINITROANILINE	S		
606-35-9		TRINITROANISOLE	S		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
606-35-9	2,4,6-	TRINITROANISOLE	S		
99-35-4		TRINITROBENZENE (DRY)	S		
99-35-4	135	TRINITROBENZENE (WET >30% WATER)	S		
2508-19-2		TRINITROBENZENESULFONIC ACID (DRY)	S		
129-66-8		TRINITROBENZOIC ACID (DRY)	S		
129-66-8		TRINITROBENZOIC ACID (WET >30% WATER)	S		
	2,4,6-	TRINITROBENZONITRILE	S		
28260-61-9		TRINITROCHLOROBENZENE	S		
918-54-7		TRINITROETHANOL	D		
		TRINITROETHYL NITRATE	D		
129-79-3	247	TRINITROFLUORENONE	S		
55-63-0		TRINITROGLYCERINE	S		
55-63-0		TRINITROGLYCEROL	S		
55-63-0		TRINITROL	S		
602-99-3	246-	TRINITRO-M-CRESOL	S		
517-25-9		TRINITROMETHANE	D		
	135-	TRINITRONAPHTHALENE (ALPHA)	D		
		TRINITRONAPHTHALENE (BETA)	S		
88-89-1		TRINITROPHENOL (DRY)	S		
88-89-1		TRINITROPHENOL (WET >30% WATER)	S		
131-74-8	2,4,6	TRINITROPHENOL, AMMONIUM SALT (DRY)	S		
	2,4,6-	TRINITROPHENYL ACETIC ACID (1% IN ACETONE AND BENZENE)	S		
	2,4,6-	TRINITROPHENYL ETHYL ALCOHOL (DISSOLVE 1% IN ACETONE & BENZENE)	S		
	246-	TRINITROPHENYL GUANIDINE (DRY)	D		
	246-	TRINITROPHENYL NITRAMINE	D		
	246-	TRINITROPHENYL TRIMETHYLOL METHYLNITRAMINE TRINITRATE, DRY	D		
606-35-9	2,4,6	TRINITROPHENYLMETHYL ETHER	S		
479-45-8		TRINITROPHENYLMETHYLNITRAMINE	S		
82-71-3	246	TRINITRORESORCINOL (DRY)	S		
82-71-3		TRINITRORESORCINOL (WET >20% WATER)	S		
55-63-0		TRINITROSAN	S		
	246-	TRINITROSO-3-METHYL NITRAMINOANISOLE	D		
		TRINITROTETRAMINE COBALT NITRATE	D		
118-96-7	246	TRINITROTOLUENE (DRY)	S		
118-96-7		TRINITROTOLUENE (WET >30% WATER)	S		
1070-00-4		TRI-N-OCTYLALUMINUM	A	W	
3248-78-0		TRI-N-OCTYLBORANE	A	W	
102-67-0		TRI-N-PROPYLALUMINUM	A		
		TRI-N-PROPYLCHLOROSILANE	A		
1070-00-4		TRIOCTYL ALUMINUM	A	W	
110-88-3	135	TRIOXANE	D		
112-73-2	5,8,11-	TRIOXAPENTADECANE	D		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

<i>Chemical CAS#</i>	<i>Prefix</i>	<i>Chemical Name</i>	<i>Reactive Chemical Stimulus 1</i>	<i>Reactive Chemical Stimulus 2</i>	<i>Reactive Chemical Stimulus 3</i>
110-88-3		TRIOXIN	D		
892-20-6		TRIPHENYLSTANNANE	W		
892-20-6		TRIPHENYL TIN HYDRIDE	W		
101-37-1		TRIPROPARGYL CYANURATE	D		
102-67-0		TRIPROPYL ALUMINUM	A	W	
17831-71-9		TREGDA	D		
26628-22-8		U 3886	S	T	
57-14-7		UDMH	S		
101-25-7		UNICEL-ND	T		
88-85-7		UNICROP DNBP	S		
1067-53-4		UNION CARBIDE ORGANOFUNCTIONAL SILANE A-172	W		
2530-85-0		UNION CARBIDE ORGANOFUNCTIONAL SILANE A-174	W		
2530-83-8		UNION CARBIDE ORGANOFUNCTIONAL SILANE A-187	W		
924-42-5		URAMINE T 80	D		
124-43-6		UREA HYDROGEN PEROXIDE	T		
124-47-0		UREA NITRATE (DRY)	S		
124-47-0		UREA NITRATE (WET >20% WATER)	S		
124-43-6		UREA PEROXIDE	T		
684-93-5		UREA, 1-METHYL-1-NITROSO-	T		
126-98-7		USAF ST-40	D		
		USP 245	T		
3851-87-4		USP 355M	T		
3006-86-8		USP 400P	T		
3006-86-8		USP 400XL	T		
686-31-7		USP 508P	T		
686-31-7		USP 570P	T		
3006-82-4		USP 690	T		
75-91-2		USP 800	T		
		USP 90 PD/MD	T		
2638-94-0		V-501	T		
13472-08-7		V-59	T		
78-67-1		V-60	T		
4419-11-8		V-65	T		
15545-97-8		V-70	T		
20858-12-2		VA-061	T		
7727-18-6		VANADIUM (5) TRICHLORIDE OXIDE	W		
7727-18-6		VANADIUM OXYTRICHLORIDE	W		
7727-18-6		VANADYL TRICHLORIDE	W		
12427-38-2		VANCIDE MANEB 80	W		
110-46-3		VAPOROLE	A		
25155-25-3		VAROR VC-R	T		
1068-27-5		VAROX 130	T		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure
 O - Strong Oxidizing Materials
 S - Shock, Friction, Static Charge
 W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)
 P - Pressure Release (for future use)
 T - Temperature Sensitive

LIST OF REACTIVE CHEMICALS

Chemical CAS#	Prefix	Chemical Name	Reactive Chemical Stimulus 1	Reactive Chemical Stimulus 2	Reactive Chemical Stimulus 3
75-35-4		VINYLDENE CHLORIDE, INHIBITED	D		
1826-67-1		VINYLMAGNESIUM BROMIDE (IN FLAMMABLE SOLVENT)	W		
3536-96-7		VINYLMAGNESIUM CHLORIDE (IN FLAMMABLE SOLVENT)	W		
111-34-2		VINYL-N-BUTYL ETHER	D		
108-57-6		VINYLS TYRENE	D		
25013-15-4		VINYLTOLUENE	D		
75-94-5		VINYLTRICHLOROSILANE	W		
754-05-2		VINYLTRIMETHYL SILANE	W		
1067-53-4		VINYL-TRIS(2-METHOXYETHOXY) SILANE	W		
22722-98-1		VITRIDE (IN SOLVENT)	W		
101-25-7		VULCACEL BN	T		
25155-25-3		VUL-CUP R	T		
534-52-1		WINTER WASH	S		
115-10-6		WOOD ETHER	D		
		X2-2614 FLUID	W		
13709-36-9		XENON DIFLUORIDE	O		
63885-01-8		ZINC AMMONIUM NITRITE	O		
14519-07-4		ZINC BROMATE	O		
10361-95-2		ZINC CHLORATE	O		
7440-66-6		ZINC DUST	W		
10196-18-6		ZINC NITRATE	O		
		ZINC PERBORATE	O		
1314-84-7		ZINC PHOSPHIDE	W		
7440-66-6		ZINC POWDER	W		
		ZIRCONIUM	A		
12070-14-3		ZIRCONIUM CARBIDE	A		
7704-99-6		ZIRCONIUM HYDRIDE	W		
12372-57-5		ZIRCONIUM NITRATE	O		
		ZIRCONIUM PICRAMATE (WET >20% WATER)	S		
		ZIRCONIUM POWDER, DRY	A		
13826-66-9		ZIRCONYL NITRATE	O		

Stimulus - Stimuli is the thermal, physical or chemical input needed to induce a hazardous reaction. (see ONYX Special Project Training Manual)

A - Air/Moist Air Exposure

O - Strong Oxidizing Materials

S - Shock, Friction, Static Charge

W - Water Exposure

D - Spontaneous Decomposition (peroxide forming, monomers & forbidden chemicals)

P - Pressure Release (for future use)

T - Temperature Sensitive